, etc.	•	
Form 3160 DEPARTM	TED STATES IENT OF INTERIOR LAND MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135
SUNDRY NOTICE AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION TO DRILL" for permit for such proposals		5. Lease Designation and Serial No. NMSF-078766
		6. If Indian, Allottee or Tribe Name
SUBMIT IN	TRIPLICATE NOV 23 2009	7. If Unit or CA, Agreement Designation
Type of Well Oil Well X Gas Well Other	Bureau of Land Managemer Farmington Field Office	₹ 8. Well Name and No. ROSA UNIT #100E
Name of Operator WILLIAMS PRODUCTION COMPANY	•	9. API Well No. 30-039-25135
3. Address and Telephone No. PO BOX 3102 MS 25-4, TULSA, OK 74101 (918) 573-3046		10. Field and Pool, or Exploratory Area BASIN DK
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1570' FSL & 870' FEL, NE/4 SE/4, SEC 21-T31N-R06W		11. County or Parish, State RIO ARRIBA, NM
CHECK APPROPRIA	TE BOX(s) TO INDICATE NATURE OF NOTICE, REPO	ORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION		OF ACTION
ξ Notice of Intent	Abandonment Recompletion	Change of Plans New Construction
Subsequent Report Final Abandonment	Plugging Back Casing Repair Altering Casing Other	Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
directionally drilled, give subsurface locations	and measured and true vertical depths for all markers and	
the tubing was stuck in the hole due to scale	build-up. We were finally able to retrieve tubi aper. We suspect a casing leak up above the PC	tarted to repair tubing on 11/12/09. We found that ing and the tubing anchor on 11/22/09. We are C formation. Our plan of action is the following:
2 Dill/		or to commencing 592 work
5. Drill out cement		RCVD DEC 1'09
6. Pressure test casing per BLM requirements.7. Clean out to PBTD with bit and scraper.		OIL CONS. DIV.
8. Land well w/ production tubing, insert pump, and rods.		DIST. 3
9. Turn well over to production.		
See alla	and Conditions of a	pprod.
14. I hereby certify that the foregoing is true and c	orrect Title Production Engineer Dat	te November 23, 2009 .

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Date 11/24/09

Title

Justin M. Stolworthy

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

BLM CONDITIONS OF APPROVAL

CASING REPAIR, WORKOVER AND RECOMPLETION OPERATIONS:

- 1. If casing repair operations are needed, obtain prior approval from this office before commencing repairs.
- 2. A properly functioning BOP and related equipment must be installed prior to commencing casing repair, workover and/or recompletion operations.
- 3. If this well is in a Seasonal Closure Area, adhere to closure stipulations.

SURFACE USE OPERATIONS:

The following Stipulations will apply to this well unless a particular Surface Managing Agency or private surface owner has supplied to BLM and operator a contradictory environmental stipulation. The failure of operator to comply with these requirements may result in assessments or penalties pursuant to 43 CFR 3163.1 or 3163.2. A copy of these conditions of approval shall be present on location during construction, drilling and reclamation activity.

An agreement between operator and fee landowner will take precedence over BLM surface stipulations unless (in reference to 43 CFR Part 3160) 1) BLM determines that operator's actions will affect adjacent Federal or Indian surface, or 2) operator does not maintain well area and lease premises in a workmanlike manner with due regard for safety, conservation and appearance, or 3) no such agreement exists, or 4) in the event of well abandonment, minimal Federal restoration requirements will be required.

STANDARD STIPULATIONS: All surface areas disturbed during work-over activities and not in use for production activities will be reseeded. This should occur in the first 90 days after completion of work-over activities.

SPECIAL STIPULATIONS:

- 1. Pits will be fenced during work-over operation.
- 2. All disturbance will be kept on existing pad.
- 3. All pits will be pulled and closed immediately upon completion of the work-over activities.
- 4. Pits will be lined with an impervious material at least 12 mils thick.