UNITED STATES

FORM APPROVED

Form 3160-5 DEPARTMENT C	OF THE INTERIOR	NOV 3 0 20	nh Budget Bureau	No 1004-0135	
(June 1990) BUREAU OF LAN	ND MANAGEMENT	MON DO TO	Expires Mare	ch 31, 1993	
			5 Lease Designation and S	Serial No	
SUNDRY NOTICES AN	D REPORTS ON WELLS Burn	oau of Land Mar	na gement		
Do not use this form for proposals to drill o	r to deepen or reentry to a diffe	rentireservoirield	()mag NMNM-99735		
	PERMIT -" for such proposals		6. If Indian, Allottee or Trib	e Name	
			_		
	TRIPLICATE				
1 Type of Well			7 If Unit or CA, Agreement	Designation	
			İ		
Oil Well X Gas Well	Other				
			8. Well Name and No.		
2. Name of Operator	·			# 420	
OGRID (163458)		Synergy 21-7-8 # 132			
Synergy Operating, LLC	<u></u>		9 API Well No.		
Address and Telephone No			20 042 24022		
P.O. Box 5513, Farmington, NM 87499 (505) 325-5449		30-043-21032			
P.O. Box 5513, Farmington, NM		9-5449	10 Field and Pool, or Explo	oratory	
4 Location of Well (Footage, Sec, T. R , M, or Sur	rvey Description)		Paoin Emitton	l Coal	
Heit D. 2001 ENII. 2701 ENII. 2001 E TOAN. DOZIN			Basin Fruitland Coal		
/ Unit D, 830' FNL, 970' FWL, Sec 8, T21N - R07W			11 County or Parish, State		
6					
320 acres (W/2)				Sandoval County, NM	
12. CHECK APPROPRIATE BOX(S) TO					
TYPE OF SUBMISSION		TYPE OF ACTION	<u> </u>		
Nation of laters		_	Observe of Blass		
Notice of Intent	Abandoment	<u> </u>	Change of Plans		
X Subsequent Report	Recompletion	-	New Construction		
X Subsequent Report	Plugging Back Casing Repair	-	Non-Routine Fracturing		
Final Abandonment Notice	I — I	_	Water Shut-Off		
Final Abandonment Notice	Altering Casing Other:	⊢	Converion to Injection		
	U Ottier.	L	Dispose Water		
			(Note Report results of multiple comp		
13. Deceribe Proposed or Completed Operations (Cia	and state all portinent details, and swe	northnort dates, includ	Completion or recompletion Report ar		
13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including, estimated date of starting work If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones of pertinent to this work					
ii well is directionally drilled give substitute locatio	ons and measured and true vertical dep	uis ioi all markers and	2011es of pertinent to this work		
11-11-09 MIRU PACE. ND WH. NU 5-1/2" Csg Swedge. Pressure Test 5-1/2" Production Casing to 500# for 30 minutes, Raise pressure					
to 1200#, Hold for 2 mins. Chart Pressures for NMOCD and BLM. Note Reservoir pressure is only 130#+/ Work performed					
prior to identifying 600# test requirement for new wells. Spoke w/ Charlie Perrin @ NMOCD. Chart Attached.					
,					
RU Blue Jet Perforators. Perforate Fruitland Coal formation: 652' to 672' (20') - 4 SPF - 80 holes					
RD & Release PACE & Blue Jet					
,					
File Completion Report					
			5	ARITA ELECTRICA	
Sundry Notice in Response to Letter dated Novel	mber 18, 2009.		######################################	CVD DEC 1'09	
			en:	T ACME 2710	
			U.	IL CONS. DIV.	
				DIST. 3	
				eran no en	
14. I hereby certify that the foregoing is true a	and correct				
111. 4. 1	16.				
Signed:	Title:	Engineering M	lanager Date:	11-30-2009	
Thomas. E. Mullins		tom.mullins@	synergyoperating.com	505-599-4905	
This space for federal or state office use					
Approved by:	Title:		Date:		

Title 18 U S C Section 1001, make it a crime for any person knowingly and wilifully to make to any department or agency of the United States any false, ficticious, or fraudulent statements.

Conditions of approval if any

 $\mathsf{NMOCD}^{\not r\gamma}$

NOV 3 0 2009

SYNERGY SYNERGY 21-7-8 # 132 PRESSURE TEST 11/11/09

