Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

RECEIVED DEC 10 2009 5. Lease Serial No.

FORM APPROVED OMB No 1004-0135 Expires July 31, 1996

ì	NΝ	ΝN	1-5	393	6A

	HO HOLO AND INLI ON IO	ON WELLSgay of Land Manage	NMNM-53936A		
Do not use uns	form for proposals to Use Form 3160-3 (APD) f	ann or reentercallon Field Offic	If Indian, Allottee or Tribe Name		
	ICATE — Other instruc		7. If Unit or CA/Agreement, Name and/or N		
1. Type of Well		(A and a see all a diff	8. Well Name and No.		
Oil Well Gas Well Name of Operator	Other *	'Amended*	Berry Federal #3		
Elm Ridge Exploration CO L	LC		9 API Well No.		
3a. Address		b. Phone No. (include area code)	30-045-31044		
PO Box 156, Bloomfield, NN		505-632-3476	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec.,	T., R, M., or Survey Description)		Bisti Lower Gallup		
1975 FNL X 2153 FWL	11. County or Parish, State				
"F" - Sec.11-T25N-R13W			San Juan County, NM		
12. CHECK APPROPRIATE BOX	K(ES) TO INDICATE NATU	RE OF NOTICE, REPORT, OR OT	HER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION				
☐ Notice of Intent ☐ Subsequent Report	Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report New Construction Recomplete				
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Temporaril Plug Back Water Disp	·		
If the proposal is to deepen directionally Attach the Bond under which the work Following completion of the involved ope	or recomplete horizontally, give subs will be performed or provide the Bon trations. If the operation results in a indonment Notices shall be filed only	including estimated starting date of any propuration locations and measured and true vertical of No on file with BLM/BIA Required subsimultiple completion or recompletion in a new after all requirements, including reclamation,	al depths of all pertinent markers and zones. sequent reports shall be filed within 30 days interval, a Form 3160-4 shall be filed once		
ocation, Rig up service unit a and pump 25bbls of hot wate PSI, tested good.* We used to as before the work over.* Let	and inspect closed loop of the soften paraffin 11-20 the same length of TBG ft pumping to tank. Good	0-09 Found 4 bad joints and r when replacing the 4 joints so I pump action. Inspected close	n surface, no good.Unseat pump replaced the TBG tested to 1000 the TBG depth is still the same		
ocation, Rig up service unit a and pump 25bbls of hot wate PSI, tested good.* We used	and inspect closed loop of the soften paraffin 11-20 the same length of TBG ft pumping to tank. Good	system,no leaks.Test pump or 0-09 Found 4 bad joints and r when replacing the 4 joints so I pump action. Inspected close	n surface, no good.Unseat pump replaced the TBG tested to 1000 the TBG depth is still the same ed loop work over tank, no		
ocation, Rig up service unit a and pump 25bbls of hot wate PSI, tested good.* We used to as before the work over.* Let	and inspect closed loop of the soften paraffin 11-20 the same length of TBG ft pumping to tank. Good	system,no leaks.Test pump or 0-09 Found 4 bad joints and r when replacing the 4 joints so I pump action. Inspected close	n surface, no good.Unseat pump replaced the TBG tested to 1000 the TBG depth is still the same red loop work over tank, no		
ocation, Rig up service unit a and pump 25bbls of hot wate PSI, tested good.* We used to as before the work over.* Let	and inspect closed loop of the soften paraffin 11-20 the same length of TBG ft pumping to tank. Good	system,no leaks.Test pump or 0-09 Found 4 bad joints and r when replacing the 4 joints so I pump action. Inspected close	n surface, no good.Unseat pump replaced the TBG tested to 1000 the TBG depth is still the same red loop work over tank, no RCVD DEC 14'		
ocation, Rig up service unit a and pump 25bbls of hot wate PSI, tested good.* We used a as before the work over.* Lei eaks,11-23-09 released to p	and inspect closed loop of er to soften paraffin 11-20 the same length of TBG ft pumping to tank. Good numper and moved off of	system,no leaks.Test pump or 0-09 Found 4 bad joints and r when replacing the 4 joints so I pump action. Inspected close	n surface, no good.Unseat pump replaced the TBG tested to 1000 the TBG depth is still the same red loop work over tank, no		
ocation, Rig up service unit and pump 25bbls of hot water PSI, tested good.* We used as before the work over.* Let eaks,11-23-09 released to pump 25-25 per service as before the work over. Let eaks, 11-23-09 released to pump 25-25 per service as a serv	and inspect closed loop of the soften paraffin 11-20 the same length of TBG ft pumping to tank. Good numper and moved off of late is 11-24-09.	system,no leaks.Test pump or 0-09 Found 4 bad joints and r when replacing the 4 joints so I pump action. Inspected close location.	n surface, no good.Unseat pump replaced the TBG tested to 1000 the TBG depth is still the same red loop work over tank, no RCVD DEC 14		
ocation, Rig up service unit and pump 25bbls of hot water PSI, tested good.* We used as before the work over.* Let eaks,11-23-09 released to pump 24. I hereby certify that the foregoing Name (Printed/Typed)	and inspect closed loop set to soften paraffin 11-20 the same length of TBG ft pumping to tank. Good numper and moved off of late is 11-24-09.	system,no leaks.Test pump or 0-09 Found 4 bad joints and r when replacing the 4 joints so I pump action. Inspected close location.	n surface, no good.Unseat pump eplaced the TBG tested to 1000 the TBG depth is still the same ed loop work over tank, no RCVD DEC 14' OIL CONS. DIV DIST. 3		
ocation, Rig up service unit and pump 25bbls of hot water PSI, tested good.* We used as before the work over.* Let eaks,11-23-09 released to pump 25-25 per service as before the work over. Let eaks, 11-23-09 released to pump 25-25 per service as a serv	and inspect closed loop set to soften paraffin 11-20 the same length of TBG ft pumping to tank. Good numper and moved off of late is 11-24-09.	system,no leaks.Test pump or 0-09 Found 4 bad joints and r when replacing the 4 joints so I pump action. Inspected close location.	n surface, no good.Unseat pump eplaced the TBG tested to 1000 the TBG depth is still the same ed loop work over tank, no RCVD DEC 14* OIL CONS. DIV DIST. 3		
ocation, Rig up service unit and pump 25bbls of hot water PSI, tested good.* We used as before the work over.* Let eaks,11-23-09 released to pump 23-09 released to pump 24. I hereby certify that the foregoing Name (Printed/Typed) Sharla I	and inspect closed loop of the same length of TBG ft pumping to tank. Good numper and moved off of late is 11-24-09. Is true and correct Duggins	system,no leaks.Test pump or 0-09 Found 4 bad joints and replacing the 4 joints so pump action. Inspected close location. Title Propage Date December 1 December 1 December 1 December 1 December 1 December 1 December 2 December 1 December 2 December 2 December 2 December 3 December 2 December 3 D	n surface, no good.Unseat pump eplaced the TBG tested to 1000 the TBG depth is still the same ed loop work over tank, no RCVD DEC 14' OIL CONS. DIV DIST. 3		
ocation, Rig up service unit and pump 25bbls of hot water PSI, tested good.* We used as before the work over.* Let eaks,11-23-09 released to pump 23-09 released to pump 24. I hereby certify that the foregoing Name (Printed/Typed) Sharla I	and inspect closed loop of the same length of TBG ft pumping to tank. Good numper and moved off of late is 11-24-09. Is true and correct Duggins	system,no leaks.Test pump or 0-09 Found 4 bad joints and r when replacing the 4 joints so I pump action. Inspected close location.	n surface, no good.Unseat pump eplaced the TBG tested to 1000 the TBG depth is still the same ed loop work over tank, no RCVD DEC 14' OIL CONS. DIV DIST. 3		

which would entitle the applicant to conduct operations thereon Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

DEC 1 1 2009

NMOCD