

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API # 30-045-27799

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company BP America	Contact Buddy Shaw
Address 200 Energy Court	Telephone No. (505) 326-9425
Facility Name Elliott SWD 1	Facility Type Injection Well

Surface Owner FEDERAL	Mineral Owner	Lease No SF 078139
--------------------------	---------------	-----------------------

LOCATION OF RELEASE

Unit Letter A D	Section 26	Township 30N	Range 9W	1270 Feet from the N	LATITUDE	580 Feet from the W	LONGITUDE	County San Juan
--------------------	---------------	-----------------	-------------	-------------------------	----------	------------------------	-----------	--------------------

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release - 20 Barrels	Volume Recovered - 0 Barrels
Source of Release: Injection Skid	Date and Hour of Occurrence: 8/26/2009 Unknown	Date and Hour of Discovery 8/26/2009 - 21:00
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCVD SEP 17 '09

OIL CONS. DIV.
DIST. 3

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

On Wednesday August 26, Production Foreman reported a spill on the Elliott SWD 1 well location. Approximately 20 barrels of produced water spilled from the injection skid. A valve was left open after repairs. All fluid soaked away into the soil around the skid. Fluid did not leave location. Average depth of soak was 7". The incident will be investigated.

Describe Area Affected and Cleanup Action Taken.* Soil on location was impacted. The area will be remediated.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Buddy Shaw	OIL CONSERVATION DIVISION	
Printed Name: Buddy Shaw	Approved by District Supervisor: [Signature]	For: CP
Title: Contract Field Environmental Coordinator	Approval Date: 10-7-09	Expiration Date:
E-mail Address: buddy.shaw@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/31/09	Phone: 505-326-9425	

* Attach Additional Sheets If Necessary

Incident # 0928133647