District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

Name of Company Surlington Resources, a wholly owned subsidiary of ConocoPhillips Company
Address 3401 E. 30th St., Farmington, NM 87402 Telephone No. 505-326-9549
Surface Owner State Mineral Owner State Mineral Owner State Lease No. B-10400-1
Surface Owner State
Unit Letter Section Township Range Feet from the 1 135' South 1135' East San Juan Latitude 36.809350 ° N Longitude 107.88410 ° W NATURE OF RELEASE Type of Release − Produced Water Volume of Release − 15 BBL Volume Recovered − 14 BBL Source of Release: Tank overflow Date and Hour of Occurrence Unknown 4/13/09 − 11:00 a.m. Was Immediate Notice Given? If YES, To Whom? Brandon Powell − via e-mail RCUD MAY 15 '09 By Whom? Gwen Frost Date and Hour − 4/16/09 − 4:30 p.m. OIL CONS. DIU. Was a Watercourse Reached? Test Yes No Not Required Test No Test Test No Test
County Feet from the Feet from the South Feet from the Fe
Latitude 36.809350 ° N Longitude 107. 88410 ° W NATURE OF RELEASE Type of Release - Produced Water Volume of Release - 15 BBL Volume Recovered - 14 BBL Source of Release: Tank overflow Date and Hour of Occurrence Unknown 4/13/09 - 11:00 a.m. Was Immediate Notice Given? If YES, To Whom? □ Yes □ No □ Not Required Brandon Powell - via e-mail RCUD MAY 15 '09 By Whom? Gwen Frost Date and Hour - 4/16/09 - 4:30 p.m. OIL CONS, DIU. Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. Describe Cause of Problem and Remedial Action Taken.* On April 13, 2009, a COPC MSO discovered that the water pit tank had overflowed due to failed telemetry. Upon discovery, the MSO shut in the well & notified a water truck to pull the pit & fluids in the pit. Approximately 14 BBL produced water was recovered. All spilled fluids remained in the berm. Describe Area Affected and Cleanup Action Taken.* All of the spilled fluids remained on location in the berm. The spill impacted soil on the ground surface in the pit. The soil in the water pit tank area was assessed for environmental impact & excavation was not required. The site was ranked at a 10 due to distance to surface water at approximately 300 feet. Depth to groundwater is greater than 100 feet at approximately 310 ft. To prevent reoccurrence, COPC will continue to monitor pit tank levels. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and
NATURE OF RELEASE
Type of Release – Produced Water Source of Release – Tank overflow Date and Hour of Occurrence Unknown Was Immediate Notice Given? Yes No Not Required Brandon Powell – via e-mail Brandon Powell
Volume of Release - Produced Water Volume of Release - 15 BBL Volume Recovered - 14 BBL
Date and Hour of Occurrence Unknown Was Immediate Notice Given? Yes No Not Required Brandon Powell − via e-mail RCUD MAY 15 '09 By Whom? Gwen Frost Date and Hour − 4/16/09 − 4:30 p.m. If YES, Volume Impacting the Watercourse. DIST. 3 Dist. 4 Di
Unknown Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required Brandon Powell — via e-mail By Whom? Gwen Frost ☐ Date and Hour — 4/16/09 — 4:30 p.m. ☐ TYES, Volume Impacting the Watercourse. ☐ Yes ☐ No ☐ Yes ☐ No ☐ TYES, Volume Impacting the Watercourse. ☐ DIST. 3 ☐ DIST. 3 ☐
Was Immediate Notice Given? Yes No Not Required Brandon Powell – via e-mail RCUD MAY 15 '09
By Whom? Gwen Frost Date and Hour – 4/16/09 – 4:30 p.m. Was a Watercourse Reached? Yes No Dist. 3 If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* On April 13, 2009, a COPC MSO discovered that the water pit tank had overflowed due to failed telemetry. Upon discovery, the MSO shut in the well & notified a water truck to pull the pit & fluids in the pit. Approximately 14 BBL produced water was recovered. All spilled fluids remained in the berm. Describe Area Affected and Cleanup Action Taken.* All of the spilled fluids remained on location in the berm. The spill impacted soil on the ground surface in the pit. The soil in the water pit tank area was assessed for environmental impact & excavation was not required. The site was ranked at a 10 due to distance to surface water at approximately 300 feet. Depth to groundwater is greater than 100 feet at approximately 310 ft. To prevent reoccurrence, COPC will continue to monitor pit tank levels. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and
By Whom? Gwen Frost Was a Watercourse Reached? Tes No Date and Hour – 4/16/09 – 4:30 p.m. If YES, Volume Impacting the Watercourse. DIST. 3 If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* On April 13, 2009, a COPC MSO discovered that the water pit tank had overflowed due to failed telemetry. Upon discovery, the MSO shut in the well & notified a water truck to pull the pit & fluids in the pit. Approximately 14 BBL produced water was recovered. All spilled fluids remained in the berm. Describe Area Affected and Cleanup Action Taken.* All of the spilled fluids remained on location in the berm. The spill impacted soil on the ground surface in the pit. The soil in the water pit tank area was assessed for environmental impact & excavation was not required. The site was ranked at a 10 due to distance to surface water at approximately 300 feet. Depth to groundwater is greater than 100 feet at approximately 310 ft. To prevent reoccurrence, COPC will continue to monitor pit tank levels. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and
Was a Watercourse Reached? Yes No If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* On April 13, 2009, a COPC MSO discovered that the water pit tank had overflowed due to failed telemetry. Upon discovery, the MSO shut in the well & notified a water truck to pull the pit & fluids in the pit. Approximately 14 BBL produced water was recovered. All spilled fluids remained in the berm. Describe Area Affected and Cleanup Action Taken.* All of the spilled fluids remained on location in the berm. The spill impacted soil on the ground surface in the pit. The soil in the water pit tank area was assessed for environmental impact & excavation was not required. The site was ranked at a 10 due to distance to surface water at approximately 300 feet. Depth to groundwater is greater than 100 feet at approximately 310 ft. To prevent reoccurrence, COPC will continue to monitor pit tank levels. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and
If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* On April 13, 2009, a COPC MSO discovered that the water pit tank had overflowed due to failed telemetry. Upon discovery, the MSO shut in the well & notified a water truck to pull the pit & fluids in the pit. Approximately 14 BBL produced water was recovered. All spilled fluids remained in the berm. Describe Area Affected and Cleanup Action Taken.* All of the spilled fluids remained on location in the berm. The spill impacted soil on the ground surface in the pit. The soil in the water pit tank area was assessed for environmental impact & excavation was not required. The site was ranked at a 10 due to distance to surface water at approximately 300 feet. Depth to groundwater is greater than 100 feet at approximately 310 ft. To prevent reoccurrence, COPC will continue to monitor pit tank levels. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and
Describe Cause of Problem and Remedial Action Taken.* On April 13, 2009, a COPC MSO discovered that the water pit tank had overflowed due to failed telemetry. Upon discovery, the MSO shut in the well & notified a water truck to pull the pit & fluids in the pit. Approximately 14 BBL produced water was recovered. All spilled fluids remained in the berm. Describe Area Affected and Cleanup Action Taken.* All of the spilled fluids remained on location in the berm. The spill impacted soil on the ground surface in the pit. The soil in the water pit tank area was assessed for environmental impact & excavation was not required. The site was ranked at a 10 due to distance to surface water at approximately 300 feet. Depth to groundwater is greater than 100 feet at approximately 310 ft. To prevent reoccurrence, COPC will continue to monitor pit tank levels. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and
Describe Cause of Problem and Remedial Action Taken.* On April 13, 2009, a COPC MSO discovered that the water pit tank had overflowed due to failed telemetry. Upon discovery, the MSO shut in the well & notified a water truck to pull the pit & fluids in the pit. Approximately 14 BBL produced water was recovered. All spilled fluids remained in the berm. Describe Area Affected and Cleanup Action Taken.* All of the spilled fluids remained on location in the berm. The spill impacted soil on the ground surface in the pit. The soil in the water pit tank area was assessed for environmental impact & excavation was not required. The site was ranked at a 10 due to distance to surface water at approximately 300 feet. Depth to groundwater is greater than 100 feet at approximately 310 ft. To prevent reoccurrence, COPC will continue to monitor pit tank levels. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and
overflowed due to failed telemetry. Upon discovery, the MSO shut in the well & notified a water truck to pull the pit & fluids in the pit. Approximately 14 BBL produced water was recovered. All spilled fluids remained in the berm. Describe Area Affected and Cleanup Action Taken.* All of the spilled fluids remained on location in the berm. The spill impacted soil on the ground surface in the pit. The soil in the water pit tank area was assessed for environmental impact & excavation was not required. The site was ranked at a 10 due to distance to surface water at approximately 300 feet. Depth to groundwater is greater than 100 feet at approximately 310 ft. To prevent reoccurrence, COPC will continue to monitor pit tank levels. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and
fluids in the pit. Approximately 14 BBL produced water was recovered. All spilled fluids remained in the berm. Describe Area Affected and Cleanup Action Taken.* All of the spilled fluids remained on location in the berm. The spill impacted soil on the ground surface in the pit. The soil in the water pit tank area was assessed for environmental impact & excavation was not required. The site was ranked at a 10 due to distance to surface water at approximately 300 feet. Depth to groundwater is greater than 100 feet at approximately 310 ft. To prevent reoccurrence, COPC will continue to monitor pit tank levels. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and
Describe Area Affected and Cleanup Action Taken.* All of the spilled fluids remained on location in the berm. The spill impacted soil on the ground surface in the pit. The soil in the water pit tank area was assessed for environmental impact & excavation was not required. The site was ranked at a 10 due to distance to surface water at approximately 300 feet. Depth to groundwater is greater than 100 feet at approximately 310 ft. To prevent reoccurrence, COPC will continue to monitor pit tank levels. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and
soil on the ground surface in the pit. The soil in the water pit tank area was assessed for environmental impact & excavation was not required. The site was ranked at a 10 due to distance to surface water at approximately 300 feet. Depth to groundwater is greater than 100 feet at approximately 310 ft. To prevent reoccurrence, COPC will continue to monitor pit tank levels. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and
excavation was not required. The site was ranked at a 10 due to distance to surface water at approximately 300 feet. Depth to groundwater is greater than 100 feet at approximately 310 ft. To prevent reoccurrence, COPC will continue to monitor pit tank levels. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and
Depth to groundwater is greater than 100 feet at approximately 310 ft. To prevent reoccurrence, COPC will continue to monitor pit tank levels. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and
to monitor pit tank levels. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and
Thereby certify that the information given decive is that all a control of the co
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.
Signature. Just OIL CONSERVATION DIVISION
Printed Name: Gwen R. Frost Approved by District Supervisor: Brand Sall For! Charlie Perrice
Title: Environmental Engineer Approval Date: 5/15/09 Expiration Date:
E-mail Address: gwendolynne.frost@conocophillips.com Conditions of Approval:

* Attach Additional Sheets If Necessary

Phone: 505-326-9549

5/14/09

Incident # nRmD 0924740-774