<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II District III
1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

				OI	PERATOR	RATOR Initial Report Final Report		
Name of Co				urces, a wholly	Contact	Kristina Kovach		
owned subsidiary of ConocoPhillips Company Address 3401 E. 30 th St., Farmington, NM 87402					Telephone N	lo. 505-32		
Facility Name San Juan 28-5 #79					Facility Typ			API # 30-039-20237
Surface Owner Federal Mineral Owner								se No. NM-010516
LOCATION OF RELEASE								
Unit Letter	Section	Township	Range		th/South Line	Feet from the	East/West Lin	ne County
M	7	T28N	R5W	1150'	South	1000'	West	Rio Arriba
Latitude 36.67167 N Longitude 107.40604 W								
NATURE OF RELEASE								
Type of Release – Condensate and produced water					Volume of Release – 1.5 BBL cond., Volume Recovered – none 4.5 BBL PW			
Source of Release: Leaking pit					1/			Date and Hour of Discovery 1/25/08 – 12:00 p.m.
Was Immedia	ate Notice (/aa 🗆 3	No. Damind	If YES, To Whom?			
☐ Yes ☐ No ☒ Not Required					OCD - Brandon Powell via email BLM - Kevin Schneider via email			
By Whom? Kristina Kovach					Date and Hour - 5/4/08 - 4:00 p.m.			
Was a Watercourse Reached? ☐ Yes ☒ No					If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*								
Describe Cause of Problem and Remedial Action Taken.* A ConocoPhillips Company employee discovered a produced water and condensate spill at the San Juan 28-5 #79 on the afternoon of 1/25/08. At the time, the volume of the spill was believed to be less than 5 BBL. The spill was due to a leaking fiberglass pit. Upon discovery, the pit was emptied, and the well was shut in. Due to road conditions, no immediate clean up was possible. Describe Area Affected and Cleanup Action Taken.* A clean up crew excavated the impacted soil, which totaled approximately 40 cubic yards, from inside the berm and transported the affected soils to Envirotech's landfarm on 4/25/08. Based on the volume of soil and the analysis of soil samples, the spill amount was determined to be 1.5 BBL of condensate and 4.5 BBL of produced water.								
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.								
Signature: Zustina Lixarch					OIL CONSERVATION DIVISION Approved by District Supervisor:			
Printed Nam	Printed Name: Kristina L. Kovach					Bolo	all !	or: Charlie Perrin
Title: Environmental Associate					Approval Dat	e: 5/12/08	Expirat	ion Date:
	ess: kristi 6/5/08			cophillips.com	Conditions of	f Approval:		Attached
Date: 5 * Attach Addi				05-326-9866		/	15	1 00

Incident It 1/2mb0929647273