<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II

1301 W. Grand Avenue, Artesia, NM 88210

District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back

side of form

Form C-141

Revised October 10, 2003

Release Notification and Corrective Action

				(OPI	ERATOR 🖂 Initia			al Report	☐ Final Report
Name of Company Burlington Resources, a wholly						Contact Gwen R. Frost				
owned subsidiary of ConocoPhillips Company							505.004	0.00		
Address 3401 E. 30 th St., Farmington, NM 87402 Facility Name Randleman #1						Telephone No. 505-326-9549 Facility Type Gas Well			API # 30-045-10698	
Facility Name Randleman #1 Surface Owner Private Mineral Owner						Facility Type Gas Well API # 30-0 Private Lease No. Fee				
Surface Owner Filvate Lease No. Fee										
LOCATION OF RELEASE										
Unit Letter	Section	Township	Range	Feet from the 1750'	Nor	th/South Line Feet from the East/West Line County South 1650' West San Juar				
K	13	T31N	R11W			South		West		San Juan
Latitude 36.895910° N Longitude 107. 9447500° W										
NATURE OF RELEASE										
Type of Release – Condensate						Volume of Release –			Volume Recovered – 0 BBL	
,						60 BBL Condensate				
Source of Release: Hole in production tank						Date and Hour of Occurrence Unknown			Date and Hour of Discovery 2/23/09 – 9:00 a.m.	
Was Immediate Notice Given?						If YES, To Whom?			ROVD MAR 2 '09	
☐ Yes ☐ No ☐ Not Required						OCD - Brandon Powell via phone			ON COME DIE	
By Whom? Gregg Wurtz						Date and Hour – 2/23/09 – 4:30 p.m.				
						If YES, Volume Impacting the Watercourse.				
Yes No If a Watercourse was Impacted, Describe Fully.*										
Describe Cause of Problem and Remedial Action Taken.* On February 23, 2009, a COPC employee discovered a hole on back side										
of production tank and an approximate 60 BBL condensate was spilled in the berm. Upon discovery, the MSO shut in										
the well and notified a Supervisor. All spilled fluids remained in the berm. None of the fluids were recoverable.										
Describe Area Affected and Cleanup Action Taken.* All of the spilled fluids remained on location. The spill impacted soil on the										
ground surface around the tank. The production tank will be removed and affected soils will be excavated. To										
prevent reoccurrence, COPC will continue to perform tank inspections.										
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and										
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger										
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability										
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health										
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.										
						OIL CONSERVATION DIVISION				
Signature: Luen R. Frost										
Signature.		•	-			Approved by District Supervisor: Bold For: Charlie Perrin				
Printed Nam	e: G	wen R. Fro	st							
Title: Environmental Engineer						Approval Date: $\frac{7}{2}$ / $\frac{3}{9}$ Expiration Date			on Date:	
		alahan = = .	-48			C4:t:	A			
E-mail Address: gwendolynne.frost@conocophillips.com						Conditions of Approval:			Attach	ed 🔲

Phone: 505-326-9549

2/24/09

^{*} Attach Additional Sheets If Necessary