

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN
(Other instru
verse side)

LOCATE*
S on re-

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/> API# 30-045-13206		5. LEASE DESIGNATION AND SERIAL NO. SF 078977	
2. NAME OF OPERATOR Compass Exploration, Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 1138, Farmington, New Mexico		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1800 feet from North line and 1140 feet from East line		8. FARM OR LEASE NAME Federal "C"	
14. PERMIT NO.		9. WELL NO. 3	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5315' G.L. 5325' K.B.		10. FIELD AND POOL, OR WILDCAT Basin Dakota	
		11. SEC. T. R. M. OR BLK. AND SURVEY OR AREA SE 1/4 NE 1/4 Section 31 T30N. R13W. NPM	
		12. COUNTY OR PARISH San Juan	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged and abandoned subject well as follows:

- (1) Pumped in 100 bbls. water and spotted 35 sx cement plug across Dakota perf.
- (2) Tested plug. Held OK.
- (3) Shot casing free at 4010' and spotted 25 sx cement plug across stub from 4060 to 3960.
- (4) Spotted 35 sx cement plug at Mesa Verde top from 2650 to 2550.
- (5) Spotted 40 sx cement plug at Pictured Cliffs top from 1140 to 1040.
- (6) Set 10 sx cement plug at surface with P&A marker 8' in cement and 4' above ground level.

Work was performed by Bedford, Inc.

Job completed 9-18-65.

RECEIVED

JUL 11 1969

U. S. GEOLOGICAL SURVEY
MOSWELL, NEW MEXICO

RECEIVED

SEP 20 1965

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED Ellis

TITLE Area Manager

DATE 9-23-65

(This space for Federal or State office use)

APPROVED

JUL 9 1969

P. T. McGRATH

DISTRICT ENGINEER

*See Instructions on Reverse Side