(S

September 2001)					OMB No. 1004-0135 Expires: January 31, 2004		
BUREAU OF LAND MANAGEMENT				5. Lease Ser	rial No.		
	Y NOTICES AND REPOR			NM-01364	12 RECENTE	1	
Do not use the	is form for proposals to d ell. Use Form 3160-3 (APD)	irili or to re-enter a for such proposals	n (		Allottee or Tribe Name	U	
abanaonoa w	m. 000 i 0iiii 0 i 00-0 (Ai D)	roi ouoii proposuis.		NA	מו צומני לחל		
CAN CAUCATION ASSESSMENT	1.10.004.002.00.710.000.00				CA/Agreement, Name and/or l	Νο. Ζ	
SUDMITTALE	IP 0 (54 TER Other) his truc				070 -		
. Type of Well	_	(0)	Dec acas 's	NA	070 Farmington.	MA	
Oil Well Gas Well	Other	<u> </u>		8. Well Nan	me and No.		
2. Name of Operator	_	GC: S		Gardner C			
Koch Exploration Company, LLC	<u> </u>	ah Dhani Na Gualai		9. API Well			
a. Address		3b. Phone No. (include	area coae)	30-045-28	d Pool, or Exploratory Area		
O Box 489, Aztec, NM 87410		(505) 334-9111			itland Coal		
. Location of Well (Footage, Sec., 331, T32N, R8W (M)	T, R., M., or Survey Description)	Jan San San San San San San San San San S			or Parish, State		
'90' FSL &750' FWL					•• • • • • • • • • • • • • • • • • • •		
BHL at TMD - 781' FSL & 775' I	FWL			San Juan,	New Mexico		
12. CHECK API	PROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, RI	EPORT, OR	OTHER DATA		
TYPE OF SUBMISSION	<u> </u>	TYP	E OF ACTION				
TITE OF SCENISSION							
Notice of Intent	Acidize	Deepen	Production (Start	/Resume)	Water Shut-Off		
Notice of filterit	Alter Casing	Fracture Treat	Reclamation		Well Integrity		
Subsequent Report	Casing Repair	New Construction	Recomplete	_	Other Sidetrack-Survey	<del>/</del>	
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Aba	indon	Report		
	Convert to Injection	Plug Back	Water Disposal				
If the proposal is to deepen direct Attach the Bond under which the following completion of the involution of the involu	d Operation (clearly state all pertinictionally or recomplete horizontally ne work will be performed or proviolved operations. If the operation real Abandonment Notices shall be for final inspection.)	r, give subsurface locations de the Bond No. on file w esults in a multiple comple	s and measured and true rith BLM/BIA. Require etion or recompletion in	e vertical depth ed subsequent i n a new interva	ns of all pertinent markers and z reports shall be filed within 30 al. a Form 3160-4 shall be filed	ones. days once	
",23# casing set @ 3042', 4-1/2 n place. 7" CIBP set@2790' on out on 10/9/03. We took a survey legrees. Survey @ 2836' S 50, E ② 3429', Survey @ S 77.98, E 10 whipstock was pulled, leaving the on 10/29/03. Well put on product	9/29/03. On 10/3/03 we set a w on the 1st 3 joints of drill pipe 2 130.07 Azimuth, Inc 3.03 degr 02.2 Azimuth, Inc 2.00 deg. TD e sidetrack hole open from 2776	whipstock oriented NE2 as we drilled out from the ees. Survey @ 2869' S. was reached on 10/13/1' to 3429'. CIBP at 2790	6.27@ 2776' to 2784' he window. Survey ( 58, E 122.16 Azimuti 03. 2nd hole was und 0' was drilled up on 1	'. A 6" windo @ 2806' N14. h, Inc 3.29 de derreamed and 0/26/03. 2-3/	ow was finished being reame .14, E 14.54 Azimuth, Inc 3. egrees. Sidetrack hole was The did cavitated. 10/25/03 the /8" tubing was landed @ 27	ed 14 D'd 67'	
Gyro Sauvey Certification and Re	eport Attached.						
				ACCEF	PTED FOR RECORD		
				1	DEC 1 12003		
14. I hereby certify that the foregoin Name (PrintedTyped) ohn Clark	ig is trate and correct	Title Distr	rict Superintendent	FARN BY_	WINGTON FILL OFFICE		
	\ \ <i>\//</i> \/\ <b>/</b>						

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Date 11/11/03

Name

(Printed/Typed) Office

Title

Date

Approved by (Signature)

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.