

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API # 30-039-20023

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company BENSON-MONTIN-GREER DRILLING CORP.	Contact Mike Dimond
Address 4900 College Blvd.	Telephone No. 505-324-5069
Facility Name Canada Ojitos Unit #11 (E-10)	Facility Type Oil Well

Surface Owner Santa Fe Forest	Mineral Owner USA	Lease No.
-------------------------------	-------------------	-----------

LOCATION OF RELEASE

Unit Letter E	Section 10	Township 25N	Range 1W	Feet from the 2145	North/South Line North	Feet from the 825	East/West Line West	County Rio Arriba
------------------	---------------	-----------------	-------------	-----------------------	---------------------------	----------------------	------------------------	----------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 10 Bbls	Volume Recovered 0
Source of Release Power Oil Tank	Date and Hour of Occurrence Jan. 15, 2007, 6:00 am	Date and Hour of Discovery Jan. 15, 2007, 6:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Voicemail left for Brandon Powell at 3:15 pm 1/15/07	
By Whom? Mike Dimond	Date and Hour 3:15 pm 1/15/07	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCVD JAN 17 2007

OIL CONS. DIV.
DIST. 3

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Oil pipeline became blocked and "kill switch" operated pneumatically froze and tank overflowed. Well was shut-in, line being thawed, and researching replacing pneumatic valves with electric.

Describe Area Affected and Cleanup Action Taken.* Affected area was all inside the tank berm. Oil could not be sucked-up due to freezing temperatures so was picked up with back hoe and taken to COU Land Farm, berm reworked and outside of tank cleaned.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Mike Dimond</i>	OIL CONSERVATION DIVISION	
Printed Name: Mike Dimond	Approved by District Supervisor: <i>Brandon Powell</i>	For: <i>Charlie Perrin</i>
Title: President	Approval Date: 1-17-07	Expiration Date:
E-mail Address: mikedimond@bmgsdrilling.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: Jan. 16, 2007	Phone: 505-325-8874	

1180711030480