<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210
District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources A

Oil Conservation Division 1220 South St. Francis Santa Fe, NM 87505∞

JAN 2002

2.4

Form C-141 Revised March 17, 1999

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Paleaca Natification and Corrective Notion

2	0030	7 245	19	ase mouin		PERATO	OR X		Înitial 1	Report X  Final Report	
Name of Company Phillips Petroleum Company						Contact R. A. Wirtaner					
						Telephone No. □ <b>505-599-3462</b>					
						Facility Type□ Water Disposal Well					
Surface Owner Mineral Owner						Leas			Lease N	ease No. \( \sum NM012735	
Bureau of Land Management Bureau of La						nd Management					
LOCATION OF RELEASE											
Unit Letter Section Township Range Feet from the 8 6 30N 6W 980'						orth/South Line   Feet from the   East/West Line   County   Rio Arriba   North   2175'   East					
NATURE OF RELEASE											
Type of Release Produced Water						Volume of	Release orrected volume)		Volume Recovered ☐ Approx. 60 bbls		
Source of Release Transfer pump would not auto start -							lour of Occurrenc	e I	Date and Hour of Discovery 1/12/44  @ 0815 hrs by PPCo Operator		
Was Immediate Notice Given?  X Yes No Not Required						If YES, To Whom?  NMOCD – Denny Foust via –e-mail.					
By Whom? Patsy Clugston – Sr. Regulatory Clerk						Date and Hour □ 1/14/02 @ 1100 hrs					
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.  N/A					
If a Watercourse was Impacted, Describe Fully.*  A watercourse was not reached.											
Describe Cause of Problem and Remedial Action Taken.*  The cause of this spill was the transfer charge pump would not auto start because of a bad battery. The bermed area was intact and no water left the bermed area on location. Key Energy sucked up the water if could and will dispose of it properly. Approx. 60 bbls was recovered and the water will be taken to Basin Disposal.											
Describe Area Affected and Cleanup Action Taken.*											
Spilled produced water did not leave location, and once the water as sucked up was hauled off, no further action was taken to remediate.											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
Signature: Patsy Cluzy In						Approved by District Supervisor:					
Printed Name: Patsy Clugston							alla 2100				
							7 /	レハE>	xpiration	Date: Attached	
Date: 1/15/02 Phone: 505-599-3454 Conditions of Approval:  * Attach Additional Sheets If Necessary										1 Ittaoned L	

n na Fozo 2234147