District I 1625 N French Dr. Hobbs, NM 88240 District II 1301 W Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St. Francis Dr., Santa Fe, NM 87505 State of New Mexico
Energy Minerals and Natural Resource

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 APR 2002

Form ( 141 Revised March 17 1999

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

3	0 030	1 2450	14				<b>OPERA</b>	TOR	, (	Initial Report X Final Repo	
Name of Cor		Energy Produ	.P		Contact	Production Foreign	(DICIPIC	13/2			
Address 330	0 N. Butler, S	uite 211, Farm	1 87401		Telephone No.						
	NICOL 105	·			(505) 324-0033 Facility Type CBM Well Site						
Facility Nam	e NEBU 485				<u>_</u>	Facility Type	CBM Well Site				
Surface Owner Bureau of Reclamation Mineral Owner: Bu						reau of Land Management Lease No. SF 079001					
					LOCATIO	ON OF RELEA	ASE				
Unit Letter	1 1 1 2 1					South Line			Line	1 7	
A 03 30N 07W			1240	240 FNL		1175 FEL			Rio Arriba		
		1	1	<u> </u>			I	1			
Type of Pale	nea Brodunad	Water	-		NATUR	E OF RELEAS			olum.	Recovered	
Type of Release Produced Water						Volume of Release ~20 bbls Volum 0 bbls				Recovered	
Source of Release: Transfer line from storage tank to SWD facility							04/02/02, ~ 09.00 am 04/02/02			Hour of Discovery , ~ 9:45 am	
Was Immediate Notice Given?							If YES, To Whom? 1. New Mexico Oil Conserv —Environmental Division (Santa Le) (505) 476 3440—Left message. 2. Denny Faust, New Mexico Oil Conserv. (505) 331-				
X Yes (within 24 hrs) No Not Required							6718 x15 3 Mark Kelly, BLM (505) 599-6380				
By Whom?							Date and Hour				
Darren Smith, Devon Energy EHS. Was a Watercourse Reached?						1 April 2, 2002, ~10:00 am 2. April 2, 2002, ~2 00 pm 3. April 2, 2002, ~3:00 pm If YES, Volume Impacting the Watercourse.					
was a water	course Reache		s X No			H TES, VOI	ume impacting the	Watercourse	ž.		
-		and Remedial			ter storage t	ank to the SWI	) facility caused th	ne leak.			
An area appropriate of the distance of the dis	oximately 600 top two inch poly once au diminary resultrom the impa- clevated with	es (~ 10 yds <sup>3</sup> ) thorization is re its from testing cted site to the respect to base	ient of the of soil fron eccived fron indicate that Navajo rese line	well site received in the impacted sit in the BLM and that chloride levels	te were reme he BOR So from the im	oved and place il samples fron pacted site are	d in the NEBU 485 the impacted site approx. 1100 mg/k	remediation and a control kg (ppm) and	cell to site w 199 m	in the water tank caused shallow surface treatment. The metal flowline will be are collected and analyzed for total g/kg from the control site. Because of pacted site are not expected to be	
are required to acceptance of and remediate	o report and/of a C-141 report contamination	or file certain re ort by the NMO on that pose a the	lease notifi CD marked reat to gro	cations and perfo I as "Final Report	rm correctiv t" does not r e water, hur	ve actions for re relieve the oper man health or the	cleases which may ator of liability sho ne environment. In id/or regulations	endanger public their open addition, N	blic hea crations MOCD	OCD rules and regulations all operato alth or the environment. The have failed to adequately investigate acceptance of a C-141 report does no	
	01 3						OIL C	CONSERVA	HON I	JIVISION	
Signature	ther (	2004					Den	y te	in		
Printed Name	: Steve Zin <b>š</b> k	,			Approved by District Supervisor: For Frank Chave Z						
Title: Produc						Approval Date	- 1/2 - 12	002 Exp	oiration	Date:	
Date: April 25, 2002 Phone: (505) 324-0033						Conditions of Approval:				Attached	

\* Attach Additional Sheets If Necessary

1 DGF 0209354246