District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

\* Attach Additional Sheets If Necessary

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

## **Release Notification and Corrective Action**

OPERATOR								Initial	Rep	ort 🛛 Final Report	
Name of Company Burlington Resources, a wholly						Contact Monica D. Johnson					
owned subsidiary of ConocoPhillips Company											
Address 3401 E. 30 <sup>th</sup> St., Farmington, NM 87402						Telephone No					
Facility Name Canyon Largo Unit #431E						Facility Type Gas Well			API # 30-039-27585		
Surface Ow	ner Fe	deral	Mineral Ov	vner	Federal Lease No. NM SF-078880						
LOCATION OF RELEASE											
Unit Letter	Section	Township Range Feet from the T25N R7W 665'				n/South Line South	Feet from the <b>905</b> '	East/West Line East		County Rio Arriba	
										NIO ATTIDA	
Latitude 36.39462° Longitude 107.53801°											
NATURE OF RELEASE  Type of Release – Produced water Volume of Release – 5 BBL Volume Recovered – 4 BBL											
Type of Release – Produced water						Date and Hour of Occurrence			Date and Hour of Discovery		
Source of Release: Pit tank overfilled						6/5/07			6/6/07 – 11:55 a.m.		
Was Immedi	Was Immediate Notice Given?						If YES, To Whom?				
☐ Yes ☐ No ☒ Not Required						Brandon Powell – OCD – via email  Mark Kelly – BLM – via email  RCUD JUN13'07					
By Whom? Monica D. Johnson						Date and Hour - 6/11/07 - 2:30 p.m. OIL CONS. DIV.			OIL CONS. DIV.		
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.				DIST. 3	
☐ Yes ☒ No  If a Watercourse was Impacted, Describe Fully.*										BIO17 C	
Describe Cause of Problem and Remedial Action Taken.* Our MSO (lease operator) discovered a 5 BBL produced water spill at the Canyon Largo Unit #431E on 6/6/07, due to the produced water pit tank overfilling. The tank overfilled because telemetry equipment for monitoring the tank level malfunctioned, the line pressure dropped, and the well unloaded more produced water than anticipated. All fluids remained in the bermed area and 4 BBL were recovered by vacuum truck.											
Describe Area Affected and Cleanup Action Taken.* All fluids remained in the bermed area and 4 BBL were recovered by vacuum truck. For remediation of the impacted soils, the soil was raked and mixed with Gator soaker. The tank level telemetry will be repaired.											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
Signatura	N A .					OIL CONS	ERVATION	N I			
Signature:	JVLO	NULL	uyon		Approved by District Supervisor: And Approved by District Supervisor:						
Printed Name	e: M	onica D. J			Approved by District Supervisor: Frank Lell For: Care						
Title: Environmental Specialist						Approval Date	val Date: 6-13-07 Expiration Date:				
			· · · · · · · · · · · · · · · · · · ·								
E-mail Address: monica.johnson@conocophillips.com						Conditions of Approval:			Attached		
Date: 6	/11/07		Phone: 5	05-326-9829							

NBP0719726619

ROMPOHING STATE