

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Dugan Production Corp.	Contact	Rodger Mullins
Address	P. O. Box 420, Farmington, NM 87499-0420	Telephone No.	(505)325-1821
Facility Name	West Bisti Unit #152**	Facility Type	Oil well

30-045-05624

Surface Owner	Federal	Mineral Owner	Federal	Lease No.	SF-078156
---------------	---------	---------------	---------	-----------	-----------

**tanks located on West Bisti #1 SWD location

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	35 34	26N	13W	2500	North	1855	East	San Juan

Latitude 36.44509 Longitude 108.18584

NATURE OF RELEASE

Type of Release	oil	Volume of Release	approx 70 bbls	Volume Recovered	approx 60 bbls
Source of Release	Pit overflowed	Date and Hour of Occurrence	11/30/07 @ approx 10:00 p.m.	Date and Hour of Discovery	12/1/07 @ approx 7:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Aztec Office NMOCD - Brandon Powell & BLM Farmington Office - Erinn Shirley		
By Whom?	Rodger Mullins	Date and Hour	12/1/07 @ approx 2:00 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

RCVD DEC 10 '07

OIL CONS. DIV.

DIST. 3

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Mechanical failure caused water knockout & oil treater to malfunction. Mechanical repairs are being worked on. Contaminated dirt being dug out and replaced with clean dirt.

Describe Area Affected and Cleanup Action Taken.*

Mostly contained within bermed area with a small amount spilling outside berm. Contaminated dirt dug out and replaced with clean dirt.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rodger Mullins</i>		OIL CONSERVATION DIVISION	
Printed Name: Rodger Mullins		Approved by District Supervisor: <i>Brandon Powell</i> For: <i>Charlie Perrin</i>	
Title: Production Foreman		Approval Date: 12-10-07	Expiration Date:
E-mail Address: rmullins@duganproduction.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: December 3, 2007 Phone: (505)325-1821			

* Attach Additional Sheets If Necessary

nBP0736035842