

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API 30-045-22019

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company BP America	Contact Kevin Hansford
Address 200 Energy Court	Telephone No. (505) 326-9279
Facility Name Moore 5A	Facility Type Gas Well

Surface Owner Federal	Mineral Owner	Lease No NMNM073382
---------------------------------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter O	Section 9	Township 30N	Range 08W	Feet from the 890	South Line	Feet from the 1515	East Line	County San Juan
-------------------------	---------------------	------------------------	---------------------	-----------------------------	------------	------------------------------	-----------	---------------------------

Latitude _____ Longitude _____



NATURE OF RELEASE

Type of Release: Condensate	Volume of Release 11 bbls	Volume Recovered 0
Source of Release: Condensate sales valve	Date and Hour of Occurrence: 2/18/07 12:00pm	Date and Hour of Discovery 2/19/06 12:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
RCVD MAR5'07 OIL CONS. DIV. DIST. 3		

Describe Cause of Problem and Remedial Action Taken.* During the site inspection the gauger noticed that the oil sales valve had frozen, was cracked and leaking. He placed a bucket under the leak, had the fluids transferred out of the tank and replaced the leaking valve.

Describe Area Affected and Cleanup Action Taken.* All fluids remained in secondary containment. The impacted soil will be cleaned up and taken to our Crouch Mesa Land Farm. An inventory will be taken of this type of valve so they can be replaced with a "drilled" type ball valve.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kevin Hansford	Approved by District Supervisor:  For: Charlie Perrin	
Title: Field Environmental Coordinator	Approval Date: 3-5-07	Expiration Date:
E-mail Address: hanske@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/2/07	Phone: 505-326-9279	

* Attach Additional Sheets If Necessary

nBP0711048876