

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

X Initial Report Final Report

Name of Company	Chevron Production Company	Contact	Michael W. Archer
Address	P.O. Box 730 Aztec, NM 87410	Telephone No.	505-326-2657 X112
Facility Name	CDP #2 / B Montoya 25 #2	Facility Type	Compressor Station
Surface Owner	Private / Fee	Mineral Owner:	Chevron Production Company
		Lease No.	API # 30-045-28674

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	25	32N	13W	1625 FSL	South	2210 FWL	West	San Juan

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release:	Volume of Release: Approx.	Volume Recovered :
Natural Gas and Lube Oil	288.45 MCF and 12 Gallons Oil/Water	7 or 8 Gallons Oil/Water
Source of Release:	Date and Hour of Occurrence:	Date and Hour of Discovery:
Compressor Station / Pit tank	12/26/2007 09:00 am	12/26/2007 11:00 am
Was Immediate Notice Given?	If YES, To Whom?	
<input type="checkbox"/> Yes X No <input type="checkbox"/> Not Required		
By Whom?	Date and Hour	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes X No	RCVD JAN 9 '08	
If a Watercourse was Impacted, Describe Fully.*	OIL CONS. DIV.	
	DIST. 3	
Describe Cause of Problem and Remedial Action Taken.*		
The Contract Pumper received a call early in the morning of 12-26 that the CDP 2 compressor had gone down. He went to location and checked out the machine and realized he would need a mechanic to get the machine back up. Pumper called Exterran's dispatch and asked for a Compressor Mechanic to be sent out. He helped the mechanic get the machine running and left location while it was warming up. The mechanic put the unit on line and called Pumper to let him know it was up. Pumper went back to check the location and found the drain valves on both compressor scrubbers open. The drain lines are piped to a 95 bbl steel pit tank.		
Describe Area Affected and Cleanup Action Taken.*		
Immediate secondary containment area around the Pit Tank. Oil/Water was picked up and put back in to tank. Five point Composite Soil sampling done and contaminated soil will be land-farmed at Envirotech's facility.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Michael W. Archer	Approved by District Supervisor:  For: Charlie Perrin	
Title: Health, Environmental & Safety Specialist	Approval Date: 1-9-08	Expiration Date:
E-mail Address: Marcher@chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1/09/2008	Phone: 1-505-326-2657 X 112	

\* Attach Additional Sheets If Necessary

n BPO800949143