

State of New Mexico
Energy Minerals and Natural Resources Department
Oil Conservation Division
2040 South Pacheco Street
Santa Fe, New Mexico 87505
(505) 827-7131

Submit 2 copies to
Appropriate District
Office in accordance
with Rule 116 on
back side of form

Release Notification and Corrective Action

OPERATOR



Initial Report



Final Report

Name Phillips Petroleum Company	Contact Robert A. Wirtanen
Address 5525 Hwy. 64, Farmington, New Mexico 87401	Telephone Number (505) 599-3462
Facility Name Blanco 204 -R API # 30-045-28776	Facility Type CBM Well-site - Fruitland Coal

Surface Owner BLM	Mineral Owner BLM	Lease No Lease # NM-012641
-----------------------------	-----------------------------	--------------------------------------

LOCATION OF RELEASE

Unit Letter M	Section 26	Township T31N	Range 8W	Feet from the 854	North/South Line South	Feet from the 1303	East/West Line West	County San Juan
-------------------------	----------------------	-------------------------	--------------------	-----------------------------	----------------------------------	------------------------------	-------------------------------	---------------------------

NATURE OF RELEASE

Type of Release produced water	Volume of Release 45 bbls	Volume Recovered 40 bbls
Source of Release pump housing on water pump	Date & Hour of Occurrence time unknown	Date & Hour of Discovery Friday March 1, 2002 (1515 hr) by Operator Jim Bowman
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not required	If YES, To Whom? NMOCD-Denny Faust by e-mail & fax; Mark Kelly by e-mail & fax State Land Office - Richard Gallegos 4601 College Blvd; Fmtn, 326-5716	
By Whom? Robert Wirtanen - Sr. EHS Splst. ...notified 3/4/02	Date and Hour 03/04/2002 1345 hr	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse NA	

If a Watercourse was impacted, describe fully (Attach additional sheets if necessary)

Spilled water did not reach a watercourse.



Describe cause of problem and remedial action taken (Attach additional sheets if necessary)


It is believed the packing gland leaked between the pump case & the pump.
Packing gland was replaced and repaired.

Describe area affected and cleanup action taken. Attach additional sheets if necessary)

all water remained inside the earthen spill - berm on the lease

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the Operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature. <i>original signed by</i> 	OIL CONSERVATION DIVISION	
Printed Name Robert A. Wirtanen	Approved by District Supervisor 	
Title Sr. Safety & Environmental Specialist	Approval Date 03/07/02	Expiration Date
Date 03/04/2002	Phone 505-599-3462	Conditions of Approval Attached <input type="checkbox"/>



Qualifies as final Report.

NDGFO206649517