

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

APR 30-045-24865

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Energen Resources	Contact Kellie Skelton
Address 2198 Bloomfield Hwy.	Telephone No. 505-566-4682
Facility Name: Federal 28-8-36 #1	Facility Type: Onshore oil and gas facility

Surface Owner Federal	Mineral Owner Federal	Lease No. NM012201
-----------------------	-----------------------	--------------------

LOCATION OF RELEASE

Unit Letter N	Section 36	Township 28N	Range 08W	Feet from the 790	North/South Line N	Feet from the 1330	East/West Line E	County San Juan County
------------------	---------------	-----------------	--------------	----------------------	-----------------------	-----------------------	---------------------	---------------------------

Latitude _N_ 36.6229 Longitude _-107.62756_

NATURE OF RELEASE

Type of Release Fire	Volume of Release NA	Volume Recovered NA
Source of Release Fire	Date and Hour of Occurrence: 1-31-07 1130	Date and Hour of Discovery 1-31-07 1130
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Charlie Perrin	
By Whom? Kellie Skelton	Date and Hour 1-31-07 1600	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	

If a Watercourse was Impacted, Describe Fully.*



NA

Describe Cause of Problem and Remedial Action Taken.* ☐ Contract employee went to service compressor unit. Put gas on unit in auto start. Tried to start 3 times but it did not start. Suction relief valve was venting. Contract employee moved to shut well in and may have rubbed up against plastic wrap causing static charge resulting in a flash fire. Employee received first and second degree burns to nose and cheek area. This was a no lost time accident.

Describe Area Affected and Cleanup Action Taken.*

Suction controller will be changed to 125 psi and the vent pipe will be piped straight up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kellie Skelton	Approved by District Supervisor:  For: Charlie Perrin	
Title: Environmental & Safety Coordinator	Approval Date: 2-5-07	Expiration Date:
E-mail Address: kskelton@energen.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: February 1, 2007 Phone: 505-566-4682		

* Attach Additional Sheets If Necessary

nBP0711035693