District J
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Revised October 10, 2003 Submit 2 Copies to appropriate

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR											
		urlington Roof Conocol		es, a wholly Company	Contact	Contact Monica D. Johnson					
Address				ngton, NM 874	Telephone	Telephone No. 505-326-9829					
Facility Nar		n Juan 32-9				Facility Type Gas Well API # 30-045-28941					
Surface Ow	ner Fe	deral		Mineral O	wner Fede	Federal Lease No. NM SF-078386			NM SF-078386		
LOCATION OF RELEASE											
Unit Letter	etter Section Township Range Feet from the No		North/South Line	Feet from the	East/West Lin	1 2					
N	15	T31N	R9W	945'	South	1485'	West		San Juan		
Latitude 36.89342° Longitude 107.77155°											
NATURE OF RELEASE Type of Release - Crude oil Volume of Release - 60 BBL Volume Recovered - 50 BBL											
						Volume of Release – 60 BBL			Volume Recovered – 50 BBL		
		nk overflow			7/24/07				Date and Hour of Discovery 7/24/07 – 5:30 p.m.		
Was Immedia	ate Notice (, ,			If YES, To Whom?					
☐ Yes ☐ No ☐ Not Required						Brandon Powell – OCD – via voicemail and email					
By Whom? Monica D. Johnson						Mark Kelly – BLM – via email Date and Hour – 7/25/07 – 2:30 p.m.					
Was a Water	course Read		JUINIS	/II		If YES, Volume Impacting the Watercourse.					
Yes No						in 125, volume impacting the watercourse.					
If a Watercourse was Impacted, Describe Fully.*											
Describe Cause of Problem and Remedial Action Taken.* A ConocoPhillips MSO discovered a crude oil spill of 60 BBL at the San Juan 32-9 Unit #5R on 7/24/07, that occurred when the weir nipple of the separator became plugged, sending all of the fluid to the oil production tank which overfilled resulting in the spill. All fluids were contained within the bermed area, with 50 BBL recovered by a vacuum truck. RCUD AUGZ*07											
OIL CC									_CONS. DIV.		
Describe Area Affected and Cleanup Action Taken.* All fluids were contained within the bermed area, with 50 BBL recovered by a vacuum truck. For remediation of the remaining impacted soils, the soils will be excavated and hauled offsite to a commercial landfarm.											
								DIST. 3			
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
Signature: \\\(\(\)\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\							DIL CONSERVATION DIVISION				
Printed Name	e: M	lonica D. Jo	hnson		Approved b	y District Supervis	sor: Brand	All "	For: Charlie Permin		
Title:	Enν	/ironmenta	l Specia	alist	Approval D	Approval Date: 8-2-07 Expiration Date:					
E-mail Addre	ess: monic	ca.johnson	@cono	cophillips.con	Conditions	of Approval:		Att	ached		
Date: 7	/26/07		Phone:	505-326-9829			(/	_		

^{*} Attach Additional Sheets If Necessary