District I District II
1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico To Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

APR 3 0 Zuu Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Oil Conservation Division

Release Notification and Corrective ActionSt. Francis Drive													
HP	= 3	30-04	OPERATOR Santa Fe, NM 87505 Initial Report Final Report										
Name of Co	mpany	Dugan Pro		Contact Kelly Miller									
		20, Farming		Telephone No. (505)325-1821									
Facility Name *Centennial Com #91S						Facility Type							
Surface Ow		ederal	r Federal Lease No. NM-10875										
*Note Spill	occurred	at the Turks	Toast Tr	-		•	entennial #91S w	vell					
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County													
F	24	30N	15W	1515	1	North	1395	ì	est	San Juan			
			<u> </u>			7							
Latitude <u>36.80279</u> Longitude <u>108.37228</u>													
NATURE OF RELEASE													
Type of Rele		Volume of Release Approx 25 bbl Volume Recovered Approx 20 bbls											
Source of Re	lease pipe	Date and Hour of Occurrence Date and Hour of Discovery 4/24/07 @ 5:30 pm 4/24/07 @ 5:30 pm						·					
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required If YES, To Whom? Aztec Office NMOCD – Brandon Powell											·		
By Whom? Paul Sikora Date and Hour 4/25/07 @ 7:55 a m													
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.							
The state of the s										CVU MHY	TU.O.	<u> </u>	
If a Watercourse was Impacted, Describe Fully.*													
NICT O													
DIST. 3													
Describe Cause of Problem and Remedial Action Taken.*													
Broken pipe caused water to spill out on ground. Vacuum truck called to vacuum pooled water & recovered 20 bbls and was placed into disposal tank for injection. Spill contained for remediation.													
Describe Area Affected and Cleanup Action Taken.*													
Spill was on flat surface, 90% of spill was on location, 10% re-seeded with Great West Reclamation. Soils remediated with construction crew. Damaged													
pipe repaired with roustabout crew. *Note - This spill occurred at the Turks Toast Transfer station on location of the Centennial #91S well.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
	should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health												
	or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
Yout6 .						OIL CONSERVATION DIVISION							
Signature: 1 A. Rodon Millar													
Printed Name	: Rodger	•	· · · · · · · · · · · · · · · · · · ·	Approved by District Supervisor: Pand Pell For: Charlie Pern'n									
Title: :-Produ	Title: @Production/Foremanco Series on by						Approval Date: 5-10-07 Expiration Date			Date:	ate:		
E-mail Addre	ss: rmulli	ins@duganpro	om.		Conditions of Approval:			No. 0.11100000000000000000000000000000000			******		
1. 数33 x 从前35。	tura, goge	74.	-					0.45	Attached	Ц			
Date: April 27, 2007 Phone: (505)325-1821 * Attach Additional Sheets If Necessary												• •	
· Auach Audh	ionai Sne	EIS II INECESS			100007107CC.W-								