

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Monica D. Johnson
Address	3401 E. 30 th St., Farmington, NM 87402	Telephone No.	505-326-9829
Facility Name	San Juan 32-8 Unit #260A	Facility Type	Gas Well
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	SF-079353
			API # 30-045-32750

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	17	T32N	R8W	1200'	South	300'	West	San Juan

Latitude 36.98046° Longitude 107.70599°

NATURE OF RELEASE

Type of Release – Produced water	Volume of Release – 25 BBL	Volume Recovered – 20 BBL
Source of Release: Stuffing box leak	Date and Hour of Occurrence 5/18/07	Date and Hour of Discovery 5/18/07 – 2:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mary Ellen Villanueva – OCD – via phone Brandon Powell – OCD – via email Mark Kelly – BLM – via email RCVD MAY23'07 OIL CONS. DIV.	
By Whom? Monica D. Johnson	Date and Hour – 5/21/07 – 12:00 p.m.	DIST. 3
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Our MSO (lease operator) discovered a 25 BBL produced water spill at the San Juan 32-8 Unit #260A on 5/18/07 due to a stuffing box leak at the wellhead. All fluids remained on location and 20 BBL were recovered by vacuum truck.

Describe Area Affected and Cleanup Action Taken.* All fluids remained on location and 20 BBL were recovered by vacuum truck. For remediation of the remaining impacted soils, the soil was raked to prevent crusting.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Monica D. Johnson</i>	OIL CONSERVATION DIVISION	
Printed Name: Monica D. Johnson	Approved by District Supervisor: <i>Brandon Powell</i>	For: Charlie Perrin
Title: Environmental Specialist	Approval Date: 5-23-07	Expiration Date:
E-mail Address: monica.johnson@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/21/07 Phone: 505-326-9829		

* Attach Additional Sheets If Necessary

nBP0719354421