

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RCVD JAN 29 2007
OIL CONS. DIV.

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

APC 30-045-33146

OPERATOR

☒ Initial Report

☐ Final Report

Name of Company XTO Energy Inc.	Contact Lisa Winn	
Address 2700 Farmington Ave, Bldg K, Ste. 1, Farmington, NM 87401	Telephone No. (505) 566-7942	
Facility Name State Gas Com BC #1F	Facility Type Gas Well	
Surface Owner State	Mineral Owner	Lease No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	32	31N	12W	695	North	765	East	San Juan

Latitude 36.8611667 Longitude 108.1148056

NATURE OF RELEASE

Type of Release Condensate	Volume of Release Approx 100 bbl	Volume Recovered Approx 0 bbl
Source of Release Load Line	Date and Hour of Occurrence 12/27/06, time unknown	Date and Hour of Discovery 01/03/07 at 1:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell	
By Whom? Kim Champlin	Date and Hour 01/03/07 at approximately 2:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse NA	

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.* ☐ An XTO Lease Operator discovered that the load line production tank valve was leaking condensate. The load line seal had been broken and the valve was partially cracked open and the bull plug was found lying on the ground. The valve was immediately shut and the tank gauged by the lease operator. Approximately 100 barrels of condensate was missing from the tank. A new seal was installed and bull plug was replaced. The San Juan County Sheriff's department and the BLM were notified of apparent vandalism/theft. Release was fully contained within the berm.

Describe Area Affected and Cleanup Action Taken.*

The condensate was contained within the berm. Approximately 72 yards of contaminated soil was excavated from the berm and hauled off site. Pit was backfilled and samples were collected by BEI.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kim Champlin</i>	OIL CONSERVATION DIVISION	
Printed Name: Kim Champlin	Approved by District Supervisor: <i>Brandon Powell</i> For: <i>Charlie Perrin</i>	
Title: Environmental Assistant	Approval Date: 1-29-07	Expiration Date
E-mail Address: Kim_Champlin@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 01/03/07 Phone: 505-566-7954		

* Attach Additional Sheets If Necessary

nBP0711037806