


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised June 10, 2003

Submit 2 copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Burlington Resources	Contact	Gregg Wurtz
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	
Facility Name	SAN JUAN 28-6 UNIT	132N	Facility Type Gas Well
Surface Owner	Fed	Mineral Owner	Fed
Lease No.			

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	32	028N	006W	1860	North	660	West	San Juan

NATURE OF RELEASE

Type of Release	Drilling 2% KCL water	Volume of Release	90 BBLs.	Volume Recovered	80 BBLs.
Source of Release	Reserve pit liner failure	Date and Hour of Occurrence	8/30/2006 3:00:00 PM	Date and Hour of Discovery	8/30/2006 3:00:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Brandon Powell		
By Whom?	Gregg Wurtz	Date and Hour	8/30/2006 3:00:00 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully \*

None

Describe Cause of Problem and Remedial Action Taken.\*

Soil supporting reserve pit liner had slope failure on one side of liner bank. The liner broke under the surface of water. The liner was not directly observed to be broken until water was released below liner level where failure occurred. Pit will be closed to OCD standards

Describe Area Affected and Cleanup Action Taken.\*

Area directly under liner. All water stayed within the area of the location and soaked into the soils under the liner.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature	OIL CONSERVATION DIVISION		
Printed Name	Approved by District Supervisor	For: Charlie Perrin	
Title: Environmental Representative	Approval Date: 8/18/06	Expiration Date:	
E-mail Address: lhasely@br-inc. com or gwurtz@br-inc.com	Conditions of Approval:	Attached	
Date: 9/13/06 Phone: (505) 326-9841 or 9537			<input type="checkbox"/>

\* Attach Additional Sheets If Necessary

hBP0627832928