<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr , Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resour

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

19 (1) (1) (2) 23 JUL 2006 PECENED OF CONS. DIVSubmit 2 Copies to appropriate District Office in accordance with Rule 116 on back DIST. 3

Form C-141 Revised October 10, 2003

side of form

Release Notification and Corrective Action 5 7

						OPERA	FOR	` Initia	l Report	\boxtimes	Final Report		
Name of Company Lance Oil & Gas, Inc.						Contact Jo Becksted							
						Telephone No. (505) 598-5601 Ext. 5558							
						Facility Type Poly Water Line NE of Navajo Tribal H #5							
	API #30-045-13101												
Surface Owner Navajo Tribe Mineral Owner						Navajo Tribe			Lease No. 14-20-603-2198				
				LOCA	TION	OF REI	LEASE						
Unit Letter	Section	Township	Range	Feet from the		/South Line Feet from the			East/West Line County				
М	13	29N	14W	705	5	South	660	West		San Juan			
		·	Lat	titude		Longitud	le						
NATURE OF RELEASE													
Type of Release Produced Water Source of Release Poly pipe water line ruptured						Volume of Release 20 bbls Volume Recovered 15 bbls Date and Hour of Occurrence Date and Hour of Discovery							
Double of Resease Toly pipe water into suprated						07/14/2006 @ 2:00 p.m. 07/14/2006 @ 2:00 p.m.							
Was Immediate Notice Given?						If YES, To Whom? Mark Kelly of BLM, Brandon of NMOCD, Steve Austin,							
✓ Yes ☐ No ☐ Not Required													
By Whom? Jo Becksted						Date and Hour 07/14/2006 @ 3:00 p.m.							
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse. N/A							
						17/1							
If a Watercourse was Impacted, Describe Fully.*													
N/A Described to the state of													
	Describe Cause of Problem and Remedial Action Taken.* Possibility of increased pressure on poly pipe line caused line to burst Describe Area Affected and Cleanup Action Taken.* The poly pipe line NE (across N36 road) burst, releasing produced water onto ground. The line was												
immediately shut in and a water truck was dispatched to suck up all fluid possible. Approximately 5 bbls of produced water impacted the soil immediately													
surrounding the rupture. The impacted soil dried rapidly, but impacted soil was raked and cleaned up by a roustabout crew.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, state, or local laws and/or regulations.													
Signature: Della Bella B						OIL CONSERVATION DIVISION							
						Approved by District Supervisor: Beandon Poull For: Charlie Persin							
Printed Name	: JoBg			District Supervisor	OI. 03	ander V	owell	Pe	rrin				
Title: Production Tech						Approval Date: 7/20/06 Expiration Date:							
E-mail Address: jbeckste@westerngas.com						Conditions of Approval:				Attached			
Date: Phone: (505) 598-5601 Ext. 5558													
Date.		. (000) 070-c	VOI LAL.										

n BP0620252773