

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

API # 30-045-26137

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company <b>BP America</b>	Contact <b>Kevin Hansford</b>
Address <b>200 Energy Court</b>	Telephone No. <b>(505) 326-9279</b>
Facility Name <b>Houck GC C1E</b>	Facility Type <b>Gas Well</b>

Surface Owner: Federal	Mineral Owner	Lease No. NMNM073922
------------------------	---------------	----------------------


**LOCATION OF RELEASE**

Unit Letter C	Section 6	Township 29N	Range 09W	Feet from the 790	North/South Line North	Feet from the 1365	East/West Line West	County San Juan
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	--------------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release: Condensate	Volume of Release: 20 barrels	Volume Recovered: <1 barrel
Source of Release: Condensate Tank	Date and Hour of Occurrence 5/8/2006 3:00 PM	Date and Hour of Discovery 5/8/2006 3:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? NA	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		



Describe Cause of Problem and Remedial Action Taken.\* Construction crew pulled onto location and discovered oil running from the top of the condensate tank on location. They shut the well in and notified BP. 20 barrels of condensate were released with very little recovered. The condensate tank also had a large amount of water in it, indicating a problem with the separator. The high tank alarm also failed to activate.

Describe Area Affected and Cleanup Action Taken.\*  
The impacted soils will be excavated and taken to BP's Crouch Mesa Landfarm for treatment. Clean soil will be hauled in to replace the excavated soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kevin Hansford</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Kevin Hansford		Approved by District Supervisor: <i>Brandon Powell</i> For Charlie Perrin	
Title: Field Environmental Coordinator		Approval Date: 5/18/2006	Expiration Date:
E-mail Address: hanske@bp.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/16/2006 Phone: 326-9279			

\* Attach Additional Sheets If Necessary

n BP0614342375