


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form



Release Notification and Corrective Action

30039 21734

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company CONOCO INC.	Contact GARY LEDBETTER
Address 3315 BLOOMFIELD HWY ; FARMINGTON, NM 87401	Telephone No. 505-324-5837
Facility Name SAN JUAN 28-7#199	Facility Type PRODUCTION FACILITY

Surface Owner BLM	Mineral Owner BLM	Lease No. SF-078500A
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter L	Section 19	Township 28N 28N	Range 7W	Feet from the 2120	North/South Line FSL	Feet from the 800	East/West Line FWL	County RIO ARRIBA
------------------	---------------	-----------------------------------	-------------	-----------------------	-------------------------	----------------------	-----------------------	-------------------

NATURE OF RELEASE

Type of Release PRODUCED NATURAL GAS-FIRE	Volume of Release <1 MCF	Volume Recovered NONE
Source of Release VENT TANK	Date and Hour of Occurrence 12/13/01 UNKNOWN	Date and Hour of Discovery 12/13/01 8:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? DENNY FOUST - NMOCD MARK KELLY - BLM	
By Whom? GARY LEDBETTER	Date and Hour 12/14/01 3:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* FROM MARKINGS ON THE VENT TANK APPARENTLY THERE WAS A FLASH FIRE AT THE VENT TANK SUPER MUFFLER DURING A VENT CYCLE (MOST LIKELY CAUSED BY STATIC ELECTRICITY), AND THE FLASH WAS LARGE ENOUGH TO IGNITED THE FUGITIVE EMISIONS AROUND A DUMP CONTROLLER STEM PACKING.
NONE *No remedial action taken.*

Describe Area Affected and Cleanup Action Taken.* NONE, NONE

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gary Ledbetter</i>	OIL CONSERVATION DIVISION	
Printed Name: GARY LEDBETTER	Approved by District Supervisor: <i>Denny Foust for Frank Chavez</i>	
Title: SHEAR SPECIALIST	Approval Date: <i>12/28/01</i>	Expiration Date:
Date: <i>12/26/01</i> Phone: 505-324-5837	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

NDG-F0135753118