

District I
1625 N French Dr, Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 045 11483
OPERATOR

Initial Report ☒ Final Report ☐

Name of Company BP	Contact Brittany Benko	
Address 200 Energy Court, Farmington, NM 87401	Telephone No. (505) 326-9235	
Facility Name Gallegos Canyon Unit 250	Facility Type Well site	
Surface Owner Indian (Navajo)	Mineral Owner Indian (Navajo)	Lease No.

LOCATION OF RELEASE

Unit Letter N	Section 14	Township 28N	Range 12W	Feet from the	North/South Line	Feet from the	East/West Line	County San Juan
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	---------------------------

NATURE OF RELEASE

Type of Release Condensate spill within berm	Volume of Release 6 bbls	Volume Recovered 5.75 bbls
Source of Release Condensate Tank	Date and Hour of Occurrence	Date and Hour of Discovery 03/26/2001 11:45 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Charlie	
By Whom? Brittany Benko	Date and Hour 3/27/2001 10:05 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken.* A BP contract pumper discovered a tank running over at the GCU 250. The pumper shut down the pumpjack, notified the foreman and then arranged to have the spill cleaned up and tank sold. Initial indications are that the high liquid level float failed, and no warning was given that the tank was about to run over. The float problem is being investigated.		
Describe Area Affected and Cleanup Action Taken.* The spill was contained inside the berm and was immediately cleaned up.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Brittany D. Benko		OIL CONSERVATION DIVISION	
Printed Name: Brittany D. Benko		Approved by District Supervisor: Denny Feart for Frank Chavez	
Title: Field Environmental Coordinator		Approval Date: 4/18/01	Expiration Date:
Date: 04/09/01	Phone: 326-9235	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

n06F0108649721