


District I
1625 N. French Dr , Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form



Release Notification and Corrective Action

3004522235

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company BP	Contact Brittany Benko
Address 200 Energy Court, Farmington, NM 87401	Telephone No. (505) 326-9235
Facility Name Gallegos Canyon Unit #267	Facility Type Well site

Surface Owner Indian (Navajo)	Mineral Owner Indian (Navajo)	Lease No. 892000844E
--------------------------------------	--------------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter G	Section 23	Township 28N	Range 12W	Feet from the	North/South Line	Feet from the	East/West Line	County San Juan
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	---------------------------

NATURE OF RELEASE

Type of Release Produced Water spill from pipeline	Volume of Release 5.75 bbls	Volume Recovered 0 bbls
Source of Release Poly pipeline	Date and Hour of Occurrence	Date and Hour of Discovery 07/23/2001 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust (left a message)	
By Whom? Brittany Benko	Date and Hour 7/23/2001 8:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.* **At approximately 10:00 a.m. on 23/7/2001 a bp pumper discovered a produced water spill from a poly gathering line at the Gallegos Canyon Unit #267. The pumper immediately began to isolate the line and then notified his foreman. It was determined that the leak resulted from a bad weld between poly lines. It was fixed and the soil saturated with produced water was excavated.**

Describe Area Affected and Cleanup Action Taken.*

The soil around the poly line was saturated with produced water. It was removed and replaced by "clean" soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Brittany D. Benko</i>	OIL CONSERVATION DIVISION	
Printed Name: Brittany D. Benko	Approved by District Supervisor: <i>Denny Foust</i> for Frank Chavez	
Title: Field Environmental Coordinator	Approval Date: 8/13/01	Expiration Date:
Date: 08/06/01	Phone: 326-9235	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

NDGF0122529421