District I
1625 N. French Dr , Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87503

Oil Conservation Division
APR 2001

RECEIVED
CON. DIV

Form C-141 Revised March 17, 1999

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action											
30 045 24735 OPERATOR CAN PROPERTY Final Report Final Report											
Name of Company BP						Contact Brittany Benkolk, DC, DC, DC, DC, DC, DC, DC, DC, DC, DC					
Address 200 Energy Court, Farmington, NM 87401 Facility Name Gallegos Canyon Unit 328						Telephone No. (505) 326-9235 Facility Type Salt Water Disposal Well					
Surface Own	ner India	n (Navajo)		Minera	Indian (N	Indian (Navajo) Lease No.					
LOCATION OF RELEASE											
Unit Letter N	Section 33	Township	Range 12W	Feet from the	North/S	South Line	Feet from the	East/We	st Line	County	
	33	29N	12 W							San Juan	
NATURE OF RELEASE											
							Volume of Release 16 bbls Volume Recovered 0 bbls				
Source of Release									nd Hour of Discovery		
Gathering Line						03/26/2001 9:15 am				2001 9:15 am	
Was Immediate Notice Given? ■ Yes □ No □ Not Required						If YES, To Whom? Charlie					
By Whom? Brittany Benko						Date and Hour 3/26/2001 10:37 am					
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.					
∐ Yes ■ No											
If a Watercourse was Impacted, Describe Fully.*											
NA											
Describe Course of Broklam and Demodial Action Taken * On the water gethering line on the CCII 228 cyctem a Flint Energy											
Describe Cause of Problem and Remedial Action Taken.* On the water gathering line on the GCU 328 system a Flint Energy Construction hand noticed water coming out of a valve can at approximately 9:15 a.m. The wells on the line											
where shut in by a BP contract pumper. It is suspected that a poly pipe to steel change over had corroded out											
and failed.											
Describe Area Affected and Cleanup Action Taken.*											
Repairs and cleanup commenced on 3/28/01.											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules											
and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may											
endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator											
of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for											
compliance with any other federal, state, or local laws and/or regulations.											
						OIL CONSERVATION DIVISION					
Signature: Duttant Lenko								j	1-Enn	st Teent	
						Approved by District Supervisor:					
Printed Name: Britany D. Benko Approved by District									<u> </u>	vank College Z	
Title: FICK	d Envi	vonmen	tal Co	povdinator	•	Approval l	Date: 4/18/1	91	Expiratio	on Date:	
Date: 04/	109/01		Phone	326-923	5	Conditions	of Approval:			Attached	
		neets If Nece	essary				F011085	6081	$\overline{}$		