District I - (505) 393-6161 P.G/Box 1980

Hobbs, NM 88241-1980

District II ~ (505) 748-1283

811 South First Artesia, NM 88210 District III - (505) 334-6178 1000 Rio Brazos Road Aztec, NM 87410

District IV - (505) 827-7131

## State of New Mexico

## Energy Minerals and Natural Resources Department

Oil Conservation Division 2040 South Pacheco Street Santa Fe, New Mexico 87505 (505) 827-7131 SEP 2001
RECEIVED
OIL CON. DIV
DIST. 3

Subrut 2 copies to Appropriate District Office in accordance

back side of form

Form C - 141

Originated 2/13/97

Release Notification and Corrective Action 2925 30045 60030 **OPERATOR** Final Report Name **Phillips Petroleum Company** Robert A. Wirtanen Address Telephone Number 5525 Hwy. 64, Farmington, New Mexico 87401 (505) 599-3462 Facility Name Facility Type San Juan 32-7 #19 Blanco Mesaverde wellsite Surface Owner Mineral Owner ease No **BLM** API well # 30-045-60030 State of NM SF-078996 LOCATION OF RELEASE Unit Letter Township North/South Line Section Range Feet from the Feet from the Rast/West Line N 31N **7W** 1650 West San Juan NATURE OF RELEASE Volume Recovered Type of Release Johnne of Release produced water (which was delivered from Phillips wellsite 32-7 #222) 120 bbls none and was about to be used for completing this well Source of Release Date & Hour of Occurrence Date & Hour of Discovery 160 bbl water storage tank connected to a 1" valve left open on a between 1900 hr on 9/4 09/05/2001 0745 hr centrifugal pump owned by Key Energy which was on-site for a well completion (rig 40) and 0745 hr on 9/5 If YES, To Whom? Was Immediate Notice Given? X Yes NMOCD-Denny Faust by e-mail & fax; Mark Kelly by fax & tele State Land Office - Richard Gallegos 4601 College Blvd; Fmtn, 326-5716 By Whom? Date and Hour Robert Wirtanen - Sr. EHS Spclst. 09/06/2001 1300 hr Was a Watercourse Reached? If YES, Volume Impacting the Watercourse Yes X If a Watercourse was impacted, describe fully (Attach additional sheets if necessary) Spilled water did not reach a watercourse. Describe cause of problem and remedial action taken (Attach additional sheets if necessary) a 160 bbl water storage tank was on-site for an upcoming wellsite completion by Key Energy's Rig 40 for Phillips Petroleum; Key Energy driver in truck #1545 left the site at 1900 hr on the 5th while leaving a 4" valve open to a "plumbed-in" centrifugal pump; there also happened to be a 1" valve in the "open" position on the pump, and this is where the water was discharged when pressures equalized after the driver left Describe area affected and cleanup action taken. Attach additional sheets if necessary) E-mail photos attached. No clean-up deemed necessary at this time. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the Operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature Approved by rant Charez Robert A. Wirtanen Printed Name original signed by..... District Supervisor Sr. Safety & Environmental Specialist Title

505-599-3462

c141-spilireport

09/06/2001

NDGF 0125727630

