## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

₹;

## RECEIVED

						IAR 29 2	
	Sundry Notices and Rep	orts on Wells			i San com est i	of Land Mi	anagement
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	· · · · · · · · · · · · · · · · · · ·		·		— Guresar	ningeaseF/A	d Office
					J.; C##		
1. Type	of Well				6.	SF-0802	
	of Well				0.	If Indian	
C	GAS					Tribe Na	ıme
					7.	Unit Agı	eement Nam
2. Name	e of Operator						
C	onocoPhillip:	S					
					<del></del> 8.	Well Na	me & Numbe
3. Addr	ess & Phone No. of Ope	rator			٥.	Florance	
	005 CD 1 1101 01 01 0 PC					1 ioi ane	V-4.1.1
РО В	Box 4289, Farmington, NI	M 87499 (505) 326-9700			9.	API Wel	l No.
						30-045-3	5066
4. Locat	tion of Well, Footage, Se	ec., T, R, M				10 0	
					10.	Field and	d Pool
Unit l	H (SENE), 1866' FNL &	t 677' FEL, Section 21, 7	129N, R9W,	NMPM		Blanco N	AV / Basin Di
					••	<b>~</b> .	• • •
					11.		and State
						San Juai	n, NM
_	Subsequent Report	Plugging Casing Repair Altering Casing		New Construction Non-Routine Fracturi Water Shut off Conversion to Injection	-		
<del></del>	Subsequent Report Final Abandonment ribe Proposed or Comple	Casing Repair Altering Casing		Non-Routine Fracturi	-		
Bince 7" connd receivement to 8/20/10 Pe Kelly Rob	Final Abandonment  ribe Proposed or Complete ement job was unsucessful permission to perf and surface, will run CBL and erfd 4 squeeze holes at 22 berts) and received permission CBL - TOC at 1800'.	Casing Repair Altering Casing  eted Operations  all and need to squeeze to squeeze at 2250' and pun	correct, callenp +/- 110bbl Type III cemelog.	Non-Routine Fracturi Water Shut off Conversion to Injection ad BLM (Steve Management and try and displaced.  and approval to perf	ason) & OCI and circulate No cement	e to surface.	If can't get  Called OCD
Since 7" condition received the seement to 8/20/10 Pe Kelly Rob 8/21/10 Rapoles at 14	Final Abandonment  ribe Proposed or Complete ement job was unsucessful permission to perf and surface, will run CBL and erfd 4 squeeze holes at 22 berts) and received permission CBL - TOC at 1800'. (405'. Pumped 98bbls Type)  O cement. Ran 3rd CBL	Casing Repair Altering Casing  eted Operations  all and need to squeeze to squeeze at 2250' and pund report.  250' and pumped 118bbls ssion to D/O cement and left Called OCD (Kelly) and referred in the Elli cement - lost returns  - TOC at 400'. Called and	correct, callenp +/- 110bbl Type III cemelog. ecceived verbaagain. No ce	Non-Routine Fracturi Water Shut off Conversion to Injection ad BLM (Steve Mails cement and try and approval to perferent to surface.	nason) & OCI and circulate No cement at 1405' and WOC.	to surface.  to surface.  d squeeze.	If can't get  Called OCD  Shot 4 squeez
Since 7" cound receive the seement to 6/20/10 Pe Kelly Rob 6/21/10 Ratioles at 14	Final Abandonment  ribe Proposed or Complete ement job was unsucessful permission to perf and surface, will run CBL and erfd 4 squeeze holes at 22 berts) and received permission CBL - TOC at 1800'. (405'. Pumped 98bbls Type)  O cement. Ran 3rd CBL	Casing Repair Altering Casing  eted Operations  all and need to squeeze to squeeze at 2250' and pund report.  250' and pumped 118bbls ssion to D/O cement and left Called OCD (Kelly) and referred in the common com	correct, callenp +/- 110bbl Type III cemelog. ecceived verbaagain. No ce	Non-Routine Fracturi Water Shut off Conversion to Injection ad BLM (Steve Mails cement and try and approval to perferent to surface.	nason) & OCI and circulate No cement at 1405' and WOC.	t to surface.  d squeeze.	Called OCD Shot 4 squeez
Since 7" condition of the condition of t	Final Abandonment  ribe Proposed or Complete ement job was unsucessful permission to perf and surface, will run CBL and erfd 4 squeeze holes at 22 berts) and received permission CBL - TOC at 1800'. (a) 105'. Pumped 98bbls Type (O cement. Ran 3rd CBL remediation needed. Call	Casing Repair Altering Casing  eted Operations  all and need to squeeze to squeeze at 2250' and pund report.  250' and pumped 118bbls ssion to D/O cement and left cement - lost returns  - TOC at 400'. Called and left BLM (Steve Mason) at the stering case of the ster	correct, callenp +/- 110bbl Type III cemelog. ecceived verbaagain. No ce	Non-Routine Fracturi Water Shut off Conversion to Injection ad BLM (Steve Mails cement and try and approval to perferent to surface.	nason) & OCI and circulate No cement at 1405' and WOC.	to surface.  to surface.  d squeeze.  ly) to contin	Called OCD Shot 4 squeez nue with drilli
Bince 7" condition received the	Final Abandonment  ribe Proposed or Complete ement job was unsucessful permission to perf and surface, will run CBL and erfd 4 squeeze holes at 22 berts) and received permission CBL - TOC at 1800'. (405'. Pumped 98bbls Type)  O cement. Ran 3rd CBL	Casing Repair Altering Casing  eted Operations  all and need to squeeze to squeeze at 2250' and pund report.  250' and pumped 118bbls ssion to D/O cement and left Called OCD (Kelly) and refer et III cement - lost returns  - TOC at 400'. Called and left BLM (Steve Mason) and the left of the lef	correct, callenp +/- 110bbl Type III cemelog. ecceived verba again. No cell received verband received	Non-Routine Fracturi Water Shut off Conversion to Injection ad BLM (Steve Management and try and approval to perferment to surface.  The provided approval from approval.	nason) & OCI and circulate No cement at 1405' and WOC.	to surface.  to surface.  d squeeze.  ly) to contin	Called OCD Shot 4 squeez nue with drilli
Bince 7" cond received the condition of	Final Abandonment  ribe Proposed or Complete ement job was unsucessful permission to perf and surface, will run CBL and erf'd 4 squeeze holes at 22 berts) and received permission CBL - TOC at 1800'. (405'. Pumped 98bbls Type of Comment. Ran 3rd CBL remediation needed. Call Roberts, add well to annual comments.	Casing Repair Altering Casing  eted Operations  all and need to squeeze to squeeze at 2250' and pum d report.  250' and pumped 118bbls ssion to D/O cement and l  Called OCD (Kelly) and r e III cement - lost returns - TOC at 400'. Called and lided BLM (Steve Mason) at l  al Bradenhead Testing.	correct, callenp +/- 110bbl  Type III cemelog.  ecceived verbagain. No cell received verbagain received	Non-Routine Fracturi Water Shut off Conversion to Injection ad BLM (Steve Management and try and approval to perferment to surface.  The provided approval from approval.	nason) & OCI and circulate No cement at 1405' and WOC.	to surface.  to surface.  d squeeze.  ly) to contin	Called_OCD Shot 4 squeez nue with drilli R 31 '10 IS. DIV.
Since 7" condition received the seement to 3/20/10 Per Kelly Roboto at 14/3/22/10 D/No further Per Kelly I	Final Abandonment  ribe Proposed or Complete ement job was unsucessful permission to perf and surface, will run CBL and erf'd 4 squeeze holes at 22 berts) and received permission CBL - TOC at 1800'. (405'. Pumped 98bbls Type of Comment. Ran 3rd CBL remediation needed. Call Roberts, add well to annual comments.	Casing Repair Altering Casing  eted Operations  all and need to squeeze to squeeze at 2250' and pund report.  250' and pumped 118bbls ssion to D/O cement and leaded OCD (Kelly) and realled OCD (Kelly) and realled EIII cement - lost returns  - TOC at 400'. Called and leaded BLM (Steve Mason) at all Bradenhead Testing.	correct, called the property of the correct called the property of the correct called the	Non-Routine Fracturi Water Shut off Conversion to Injection  d BLM (Steve Management and try and displaced and approval to perfer ement to surface.  The surface of the sur	No cement at 1405' and WOC. a OCD (Kell	to surface.  to surface.  d squeeze.  ly) to contin  RCVD MAI  DIL CON  DIS	Called OCD Shot 4 squeez nue with drilli R 31 '10 IS. DIV.
Bince 7" cond received the condition of	Final Abandonment  ribe Proposed or Complete ement job was unsucessful permission to perf and surface, will run CBL and erf'd 4 squeeze holes at 22 berts) and received permission CBL - TOC at 1800'. (405'. Pumped 98bbls Type of Comment. Ran 3rd CBL remediation needed. Call Roberts, add well to annual comments.	Casing Repair Altering Casing  eted Operations  all and need to squeeze to squeeze at 2250' and pund report.  250' and pumped 118bbls ssion to D/O cement and leaded OCD (Kelly) and realled OCD (Kelly) and realled EIII cement - lost returns  - TOC at 400'. Called and leaded BLM (Steve Mason) at all Bradenhead Testing.	correct, callenp +/- 110bbl Type III cemelog.  ecceived verbagain. No cell received verbagain received  Complete Notify	Non-Routine Fracturi Water Shut off Conversion to Injection ad BLM (Steve Management and try and approval to perferment to surface.  The provided approval from approval.	No cement at 1405' and WOC. OCD (Kell PRIOR T	to surface.  to surface.  d squeeze.  ly) to continue CVD MAI  OIL CON  DIS  chnician	Called OCD  Shot 4 squeez  nue with drilli  R 31 '10  IS. DIV.  Date 3/26/10
Since 7" condition of the condition of t	Final Abandonment  ribe Proposed or Complete ement job was unsucessful permission to perf and surface, will run CBL and erfd 4 squeeze holes at 22 berts) and received permission CBL - TOC at 1800'. Of Communication (CBL) and Proposed 98bbls Type (O cement. Ran 3rd CBL) remediation needed. Call Roberts, add well to annually certify that the foregree for Federal or State Office.	Casing Repair Altering Casing  eted Operations  all and need to squeeze to squeeze at 2250' and pund report.  250' and pumped 118bbls ssion to D/O cement and left called OCD (Kelly) and refer e III cement - lost returns  - TOC at 400'. Called and left BLM (Steve Mason) at all Bradenhead Testing.  Tomas ice use)	correct, called the property of the correct called the property of the correct called the	Non-Routine Fracturi Water Shut off Conversion to Injection  d BLM (Steve Management and try and displaced and approval to perfer ement to surface.  The surface of the sur	nson) & OCI and circulate No cement at 1405' and WOC. n OCD (Kell	to surface.  to surface.  d squeeze.  ly) to continue CVD MAI  OIL CON  DIS  chnician	Called OCD Shot 4 squeez nue with drilling 31 '10 S. DIV. Date 3/26/10
APPROVE	Final Abandonment  ribe Proposed or Complete ement job was unsucessful permission to perf and surface, will run CBL and erfd 4 squeeze holes at 22 berts) and received permission CBL - TOC at 1800'. Of the complete of the c	Casing Repair Altering Casing  eted Operations  all and need to squeeze to squeeze at 2250' and pum d report.  250' and pumped 118bbls ssion to D/O cement and left called OCD (Kelly) and referred to the HII cement - lost returns  - TOC at 400'. Called and left BLM (Steve Mason) at all Bradenhead Testing.  Toing is true and correct.  Tamra  ice use)  Title	correct, called the property of the correct called the property of the correct called the	Non-Routine Fracturi Water Shut off Conversion to Injection  d BLM (Steve Management and try and displaced and approval to perfer ement to surface.  The surface of the sur	nson) & OCI and circulate No cement at 1405' and WOC. n OCD (Kell	to surface.  to surface.  d squeeze.  ly) to continue CVD MAI  OIL CON  DIS  chnician	Called OCD Shot 4 squeez nue with drilli R 31 '10 IS. DIV. Date 3/26/10
Since 7" condition of the Religion of the Reli	Final Abandonment  ribe Proposed or Complete ement job was unsucessful permission to perf and surface, will run CBL and erf'd 4 squeeze holes at 22 berts) and received permission CBL - TOC at 1800'. (105'. Pumped 98bbls Type'/O cement. Ran 3rd CBL remediation needed. Call Roberts, add well to annually certify that the foregous certify that the foregous certify that the foregous CON OF APPROVAL, if a section 1001, makes it a crime for any person 1001.	Casing Repair Altering Casing  eted Operations  all and need to squeeze to squeeze at 2250' and pum d report.  250' and pumped 118bbls' ssion to D/O cement and leaded OCD (Kelly) and realificement - lost returns  - TOC at 400'. Called and leaded BLM (Steve Mason) at Bradenhead Testing.  Tomas ice use)  Title any:  Title any:	correct, callenp +/- 110bbl Type III cemelog. ecceived verba again. No cell received verband received  Conductive Notify Test. Sessions	Non-Routine Fracturi Water Shut off Conversion to Injection de BLM (Steve Mass cement and try and approval to perferent to surface.  The Staff Reserved Staf	nson) & OCI and circulate No cement at 1405' and WOC. n OCD (Kell	to surface.  to surface.  d squeeze.  ly) to continue CON MAI  OIL CON  chnician  Date/AR	Called OCD Shot 4 squeez nue with drilli R 31 '10 IS. DIV. Date 3/26/10