## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Sundry Notices and Reports on Wel	ls		
*****		RECEIVED	5.	Lease Number SF-080712-A
1.	Type of Well GAS	JUN 24 2010	6.	If Indian, All. or Tribe Name
2.	Name of Operator <b>BURLINGTON</b>	Sureau of Land Manager St. Famingion Field Office	7.	Unit Agreement Name San Juan 30-6 Unit
	RESOURCES OIL & GAS CO	OMPANY LP		
3.	Address & Phone No. of Operator	· · · · · · · · · · · · · · · · · · ·	8.	Well Name & Number San Juan 30-6 Unit 53B
	PO Box 4289, Farmington, NM 87499 (50	05) 326-9700	9.	API Well No.
	Location of Well Footogo See T D M			30-039-30744
4.	Location of Well, Footage, Sec., T, R, M Surface: Unit M (SWSW), 645' FSL & 7	70' FWL, Section 29, T30N, R6W, NMPM	10.	Field and Pool Blanco MV / Basin DK
	Bottomhole: Unit N (SESW), 730° FSL & 123	2 1930' FWL, Section 29, T30N, R6W, NMPM 1935	11.	County and State Rio Arriba, NM
12.		ICATE NATURE OF NOTICE, REPORT, OT	HER	DATA
		andonment Change of Plans	_X	Other – Casing Report
	X Subsequent Report Plus	completion New Construction gging Non-Routine Fracturing		CCVD JUN 25 10
27		sing Repair Water Shut off ering Casing Conversion to Injection		OIL CONS. DIV. DIST. 3
13.	Describe Proposed or Completed Operat	tions		
05// LTC 10b cell @ scar 393 disp 05/ to 8 set cell Soc	08/2010 RIH w/ 8 3/4" bit. Tag & DO cmt. Dri 2C set @ 4305' w/ ST@3572'. 05/12/10 RU to bls) Type III cmt w/ 1% CACL, .25pps cellofl oflake, 5pps LCM-1, 8% bentonite, .4% SMS, 3:00hrs. Open ST & circ. 26bbls cmt to surfar venger 19sx (57cf-10bbls) Premium lite cmt w/ sx (837cf-149bbls) Premium lite cmt w/ 3% C laced w/ 141bbls FW. Bump plug & close ST (3/2010 RIH w/ 6 1/4" bit. Drill out ST@3572 598' (TD) TD reached 5/18/10. Circ. hole & F @ 8596', 05/19/10 RU to cmt. Pre-flush w/ 10 oflake, .3% CD-32, 6.25pps LCM-1, 1% FL-5/2	to 600#/30min @ 00:00hrs on 5/7/10. Test - OK. filled ahead to 4315' - Inter TD reached 5/10/10. Circ o cmt. 1st Stage - Pre-flush w/ 10bbls GW, 2bbls FW ake, 2% FL-52. Tail w/ 138sx (190cf-34bbls) Type .4% FL-52. Drop plug & displaced w/ 40bbls FW, 10bbls GW, 25pps celloflake, 5pps LCM-1, .4% FL ACL, 8% bentonite, .25pps celloflake, .4% FL-52, 5p. Circ. 48bbls cmt to surface. Plug down @ 18:44hr '. PT 7" csg to 1500#/30min @ 7:30hrs on 5/13/10. TRIH w/ 201jts. total. 30jts, 4 1/2", 11.6#, L-80 BTC abbs GW, 2bbls FW. Pumped scavenger 9sx (28cf-5bg). Tail w/ 323sx (640cf-114bbls) Type III cmt w/ .39 //. Drop plug & displaced w/ 133bbls FW. Bump plug 8:00hrs on 5/20/10.	Pum: Pum: 28bbls GW, -52, 89 pps LCrs on 5, Test - (and 17) pbbls) P. % CD-	ped scavenger 20sx (55cf-tw/ 3% CACL2, .25pps s MW. Bump plug. Plug down, 10bbls FW. Pumped bentonite, .4% SMS. Lead w M-1, .4% SMS. Drop plug & 1/12/10. RD cmt. WOC. DK. Drilled ahead w/ 6 1/4" bir lits, 4 1/2", 11.6#, L-80 LT&C remium life cmt w/ .25pps 32, 1.2% FL-52, .4% LW-6, 29
	will be conducted by Completion Rig. Resul			
	I hereby certify that the foregoing is true			, 1001
Sig	ned Instal Taloya	Crystal Tafoya Title Regulatory Te	chnici:	EPTED FOR RECORD
— (Th	is space for Federal or State Office use)			JUN 2 4 2010
ΑP	PROVED BY	Title	EAC	Date MINGTON FIELD OFFICE
	8 U.S.C. Section 1001, makes it a crime for any person knowingly and w	ullfully to make any department or agency of	BY	BAIN 4

NMOCD