Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVE	Ĺ
OMB No. 1004-013	í
Expires July 31 20	1

5. Lease Serial No. NMSF 078875

Do not use this	form for proposals t Use Form 3160-3 (A	to drill or to	re-enter an	S: F	6. If Indian, Allottee	or Trib	e Name		
	7. If Unit of CA/Agreement, Name and/or No.								
SUBMIT IN TRIPLICATE – Other instructions on p				Jage Z.			anyon Largo Unit		
1. Type of Well Oil Well Gas V	Jl	JL 15 2010)	8. Well Name and No. Canyon Largo Unit #357					
2, Name of Operator Huntingotn Energy, L.L.C.	Farmi	mington Field Office		9. API Well No. 30-039-23876					
3a. Address 908 N.W. 71st St Oklahoma City, OK 73116	3b. Phone No. (include area code) 405-840-9876			10. Field and Pool or Exploratory Area Devils Fork Gallup					
4. Location of Well <i>(Footage, Sec., T.,</i> SE/4 790 FSL & 790 FEL Sec. 29, T25N-R6W)	11. Country or Rio Arriba Co.							
12. CHEC	CK THE APPROPRIATE BO	X(ES) TO INDIC	CATE NATURE	OF NOTIC	E, REPORT OR OT	HER DA	ATA		
TYPE OF SUBMISSION			TYP	E OF ACT	ON				
✓ Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat		Production (Start/Resume) Reclamation		Water Shut-Off Well Integrity			
Subsequent Report	Casing Repair		onstruction	Reco	mplete ,		Other		
Final Abandonment Notice	Change Plans Convert to Injection	✓ Plug and Abandon ☐ Plug Back		_ `	Temporarily Abandon Water Disposal				
determined that the site is ready for Huntington Energy, L.L.C. plans 1. MICU. 2. Unseat Pump. Hot oil if ne 3. ND WH. NU BOP. Rel TA 4. MV Plug @ 9050': Wireling 5. Picture Cliff plug 2680'-25 6. Kirtland/Ojo plug combine 7. Casing Plug - Circulate ce bradenhead. Install dry ho	s to plug and abandon the seded. POOH w/polish rod C. COOH w/tubing. RU Basset plug at 3850'. Dump 380' & Fruitland plug 2550' and pump 30 sx Neat fror ment from 380' to Surface the marker.	, rods, and 1 1/4 sin WL & set Cl 35' of emt on ple - 245 0'. Combin n 22 9 0' to top of - 5 0 sx. ND BO	t" pump. LD all. BP @ 6000'. D rg. from 4234 e and pump 30 f 1900'. P, fill casing to	Note condump bail 3	lition of all. 5' cmt on top of plu Chacra plus rom 270 0' - top of	from 2 40 0') 2 375			
- Nacimiento plus	65'-565' incide +	overida 4	" c-113.		RCVD JUL 20'10				
. •			Notif , pric	y NMOCI or to begi operatio	nning	OIL	CONS. DIV.		
:		``	,				NC O		
14. I hereby certify that the foregoing is to Catherine Smit	ue and correct. Name (Printed	l/Typed)							
		1	Title Regulator	у					
Signature atherno	Smith	I	Date 07/12/201	0					
	THIS SPACE	FOR FEDER	AL OR STA	TE OFF	ICE USE				
Approved by							HH 4 C 0040		
	ned: Stephen Mason		Title			Date	JUL 1 6 2010		
Conditions of approval, if any, are attached that the applicant holds legal or equitable to entitle the applicant to conduct operations to	tle to those rights in the subjec	not warrant or cert t lease which would	tify d Office			-			

Title 18 U.S C Section 1001 and Title 43 U.S C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: 357 Canyon Largo Unit

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made:
- a) Place the Mesaverde plug from 4224' 4124'.
- b) Place a cement plug from 3515' 3415' to cover the Chacra top.
- c) Place the Pictured Cliffs/Fruitland plug from 2680' 2375'.
- d) Place the Kirtland/Ojo Alamo plug from 2250' 1910'.
- e) Place the Nacimiento plug from 656' 565' inside and outside the 4 1/2" casing.
- f) Place the Surface plug from 273' to surface inside and outside the 4 1/2" casing.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.