	Form 3160-5
<	(August 2007)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.  SUBMIT IN TRIPLICATE - Other instructions on reverse side.					NMNM5991				
					6. If Indian, Allottee or Tribe Name				
						7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well						8. Well Name and No JUNE JOY 2			
2. Name of Operator	Gas Well O		JOHN CA	ΙΕΎΔΝΙ	)EB		9. API Well No.		
DUGAN PROD	DUCTION COF	RPORATIŒMail: johncalexa	inder@duga	nproducti	on.com	30-045-23893-00-S2			
3a. Address  FARMINGTON	3a. Address 3b. Phone Ph: 505-FARMINGTON, NM 87499							Field and Pool, or Exploratory BISTI LOWER GALLUP	
		T., R., M , or Survey Description	<u> </u>		<del></del>		11. County or Parish,	and State	
	Sec 25 T24N R10W NWNE 0790FNL 1670FEL 36.29004 N Lat, 107.84428 W Lon				SAN JUAN COUNTY, NM			UNTY, NM	
12.	CHECK APP	ROPRIATE BOX(ES) TO	INDICAT	E NATU	JRE OF N	OTICE, RE	PORT, OR OTHER	R DATA	
TYPE OF SUB	MISSION			**	TYPE O	ACTION			
Nation of Late		Acidize	Deepen Prod		Producti	on (Start/Resume)	Water Shut-Off		
Notice of Inter		Alter Casing	□ Fr	acture Tr			tion	☐ Well Integrity	
☐ Subsequent R	eport	Casing Repair	□ Ne	ew Consti	ruction	Recomp	lete	Other	
Final Abandor	nment Notice	Change Plans	· ⊠ Plı	ug and Al	bandon	☐ Tempora	rily Abandon	<del>_</del>	
2		Convert to Injection	□ Ph	lug Back Water Disposal			isposal		
following completi testing has been co determined that the	on of the involved mpleted. Final A site is ready for f	rk will be performed or provide I operations. If the operation res- bandonment Notices shall be file inal inspection.)	ults in a multi	ple comple	etion or reco	mpletion in a n	ew interval, a Form 316	0-4 shall be filed once and the operator has	
Plan to plug we									
Set cast iron plu	ug at 4673' (Ga V cement pluc	allup top 4720', top Gallup	perf 4723')			OIL CONS. DIV.			
Set Type Vicem	ient plug 1153 Ojo Alamo top	on top of plug to 4541. '- 2207' Mesaverde top 21 '- 1496' Pictured Cliffs top 362') circulate coment to 5	1446', Fruit <del>arface</del> . 💤	2 823	- 601'		DIS he Kirrland /050h		
Notify NMOC	T) 24 hm	Suctace plu	y from	259 6	o surta	: e			
prior to beg operation	ginning	inside + our s	ide the	4/2 (	iesirj.				
14. I hereby certify the	5 5	truc and correct. Electronic Submission #8 For DUGAN PRODUC nmitted to AFMSS for proce	TION CORP	<b>PRÁTION</b>	I, sent to	the Farmingto	ón		
Name (Printed/Type	d) JOHN C	ALEXANDER		Title	VICE PR	ESIDENT			
Signature	Signature (Electronic Submission)				07/13/20	10			
		THIS SPACE FO	R FEDER	AL OR	STATE (	FFICE US	<b>E</b>		
Approved By STEP	Approved By STEPHEN MASON			TitlePE	TROLEU	JM ENGINEER Date		Date 07/15/2016	
	holds legal or equ	. Approval of this notice does n itable title to those rights in the set operations thereon.		Office	Farmingto	on			
				•					

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment	to	notice	of
Intention to	Ah	andon	

Re: Permanent Abandonment

Well: 2 June Joy

## **CONDITIONS OF APPROVAL**

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made:
- a) Bring the top of the Gallup plug to 4542'.
- b) Place the Kirtland/Ojo Alamo plug from 823' 601'.
- c) Place the Surface plug from 259' to surface inside and outside the 4 1/2" casing.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.