Form 3160-5 (August 2007)

entitle the applicant to conduct operations thereon

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

FORM APPROVED
OMB NO 1004-013
Expires July 31, 2010

5. Lease Serial No.

NMSF-	0	۱7	8	2	1	Ξ.
-------	---	----	---	---	---	----

6. If Indian, Allottee or Tribe Name

abandoned well. Use For				E 3.		
SUBMIT IN TRIPLICA	TE - Other instruction	ons on page 2RLC	EIVE	7. If Unit or CA/A	greement, Name and/or No	
I. Type of Well Oil Well X Gas Well Other	Gas Well Other AUG 0 5 2010				8. Well Name and No. ARNIE #4T	
2. Name of Operator		Farmingto	n Field Offic	c ⊛		
XTO ENERGY INC. 3a. Address				API Well No.		
382 CR 3100 AZTEC, NM 87410	3b. Phone No. (include area code) 505-333-3176			30-045-32167 10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey)	Description)	1 303-333-3170		BASIN FRUITL	•	
1770' FNL & 1545' FWL SENW SE	C.25(F)-T30N-R1	3W N.M.P.M.				
				11. County or Par	ish, State	
				SAN JUAN	NM	
12. CHECK APPROPRIATI	E BOX(ES) TO INI	DICATE NATURE OF NO	TICE, REPO	ORT, OR OTHER I	DATA	
TYPE OF SUBMISSION		ТҮРЕ	E OF ACTION			
X Notice of Intent	Acidize	Deepen	Production	n (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamati	on	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomple	te	Other	
\mathcal{V}	Change Plans	X Plug and Abandon		ily Abandon	- Cities	
Final Abandonment Notice			Water Dis	-		
CZ.	Convert to Injects	on Plug Back	water Dis	sposai		
XTO Energy Inc. intends to plug a		_				
				RCVD AUG 10'10		
	Notify NMOCD 24 hrs prior to beginning operations		OIL CONS. DIV.			
				DIST. 3		
		,				
14. I hereby certify that the foregoing is true and correct						
Name (Printed/Typed) TEENA M. WHITING		Title REGULAT	Title REGULATORY COMPLIANCE TECHNICIAN			
Signature Leena M. Whit	rag	Date 8/4/2010				
THI	S SPACE FOR FEI	DERAL OR STATE OFF	ICE USE			
Approved by		Title		Date	AUG 0 9 2010	
Original Signed: Stephen Conditions of approval, if any, are attached. Approval of this no the applicant holds legal or equitable title to those rights in the su	Mason tice does not warrant or cer ubject lease which would	tify that Office				

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction



CLJ	
TWD	
Approved	

Arnie #4T P&A Fruitland Coal UL F, Sec 25, T30N, R13W San Juan County, New Mexico

AFE# / WELL#

1002019 / 67908

Formation:

FC

Production Csg:

4-1/2", 10.5# CSG @ 1,930'.

PBTD:

1.909'

Tubing:

2-3/8" x 30' OEMA, SN, 55 jts 2-3/8" tbg. SN @ 1,776'. EOT @ 1,807'

Perforations:

1,736' - 1,762'

Current Prod:

0 MCFPD

Plug and Abandonment Procedure

- 1. Check anchors. MIRU PU.
- 2. TOH & LD rods & pmp.
- 3. ND WH. NU BOP.
- 4. TIH & tag fill (PBTD @ 1,909'). PT tbg. TOH & visually inspect tbg.
- 5. TIH 4-1/2" CIBP on tubing. Set CIBP @ 1,700'.
- 6. Load casing with water and pressure test to 550 psig for 30 minutes. Record test on chart. If casing does not test, spot and tag subsequent plugs as appropriate.
- 7. MIRU cement truck.
- 8. Pump 4 sx class "G" cement (15.6 ppg, 1.18 cuft/sx yield) down tubing from 1,700' 1,650'.
- 9. Pump 12 sx class "G" cement (15.6 ppg, 1.18 cuft/sx yield) down tubing and spot balance plug from 1,360 1,460 (volume calculated with 50% excess).
- 10. ND BOP.
- 11. Pump 34 sx class "G" cement (15.6 ppg, 1.18 cuft/sx yield) down tubing and spot balance plug from surface 483'.
- 12. LD all tubing. RDMO PU.
- 13. WOC 4 hours.
- 14. Cut off wellhead. Fill in casing as needed with cement. Install P&A marker.
- 15. Cut off anchors and reclaim location.

Regulatory Requirements C-144 Form


NOI for P&A on form C-103

Submit a post-work sundry on form C-103 which details the P&A work and location work within 30 days of completing all required restoration work.

Materials

1 flowback tank 50 sx cl "G" cmt Cement truck 1 – 4-1/2" CIBP P&A marker

KB: 5,735' GL: 5,734' KB CORR: 1'





www.peloton.com

XTO - Wellbore Diagram

Page 1/1

Report Printed: 4/8/2010

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment	to	notice	of
Intention to	Ab	andon	:

Re: Permanent Abandonment Well: 4T Arnie

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made:
- a) Place the Fruitland plug from 1557' 1457'.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.