Form 3160-5 (August 2007)

DEPARTMENT OF THE INTERIOR RECEIVED BUREAU OF LAND MANY

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No. NMNM-0560223

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS 13 2010 of use this form for process. Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals and are a such proposals and a such proposals are a such proposals and a such proposals and a such proposals are a such p

7 ISTILL OF CA /A					
SUBMIT IN TRIFLICATE - Other instructions on page 2.	7. If Unit of CA/Agreement, Name and/or No.				
1. Type of Well Oil Well Gas Well Other S. Well Name and No. Frew Federal #1 Pc					
2. Name of Operator 9. API Well No. Running Horse Production Co. 30-045-22052					
3a. Address PO Box 369 Ignacio, CO 81137 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 970-563-5167					
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 1800' FSL, 1600' FEL, Sec 20 T26N R12W 1800' FSL, 1600' FEL, Sec 20 T26N R12W 11. Country or Parish, State San Juan County, NM					
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA					
TYPE OF SUBMISSION TYPE OF ACTION					
Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Recomplete Other					
Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Convert to Injection Plug Back Water Disposal					
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Red Willow Production Company proposes to plug and abandon this well per the following procedure: Move on and rig up a pulling unit. Pump 20 bbls water. Plug #1 from 1156' - 675' with 52 sxs Class B cement (40% excess, long plug) to fill the Pictured Cliffs perforations and cover the PC and Fruitland tops. WOC and tag cement. Top off plug #1 as necessary. Circulate the well clean; pressure test the casing to 800 PSI. Perforate at 150. Establish circulation. Plug #2 spot approximately 45 sxs from 150' to surface to cover the surface casing shoe and Kirtland top, circulate good cement out bradenhead. Cut off the wellhead. Top off cement if necessary and set a p&a marker. RD and MOL.					
Notify NMOCD 24 hrs prior to beginning operations RCVD AUG 24 '10 OIL CONS. DIV. DIST. 3					
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) J. Dusty Mars Title Acting Drilling & Production Manager					
Signature Date 08/12/2010					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by					
Original Signed: Stephen Mason Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any	, falsa				

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment	to	notice	of
Intention to	Αb	andon	:

Re: Permanent Abandonment

Well: 1 Frew Federal

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made:
- a) Bring the top of the Pictured Cliffs/Fruitland plug to 660'.
- b) Place the Kirtland/Surface plug from 182' to surface inside and outside the 4 1/2" casing.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.