	o Appropriate District	State o.	f New Mexico		Form C-103	
Office District I	·	Energy, Mineral	s and Natural Resources	·	Jun 19, 2008	
	r., Hobbs, NM 88240			WELL API N	O	
District II		OIL COMEED	NATION DIVISION		30-045-35104	
District III OIL CONSERVATION DIVISION 1220 South St. Francis Dr.			5. Indicate Ty	ype of Lease		
District III	2d Asstan NIM 97410	1220 Sou	th St. Francis Dr.	STATE		
District IV	Rd., Aztec, NM 87410	Santa I	Fe, NM 87505		Gas Lease No.	
	s Dr., Santa Fe, NM	•	,	o. State on a	V-88-1	
87505					V. 00 1	
	SUNDRY NOTIC	ES AND REPORTS (ON WELLS	7. Lease Nam	ne or Unit Agreement Name	
			EPEN OR PLUG BACK TO A	s	usco 16 State	
	SERVOIR. USE "APPLICA	TION FOR PERMIT" (FO	RM C-101) FOR SUCH		•	
PROPOSALS.)				8. Well Numl	her 3	
		as Well 🛛 Other	· .			
2. Name of O	perator			9. OGRID Ni	umber	
Burlington Resources Oil Gas Company LP					14538	
3. Address of	Operator			10. Pool nam	e or Wildcat	
P.O. Box 4289	Farmington, NM 87	499-4289		Alb	oino Pictured Cliffs	
4. Well Locat		*				
Unit I	_etter <u>G</u> : 1600	feet from the	North line and	feet fro	om the <u>East</u> line	
Section	on 16	Township 321	N Range 8W	NMPM S	San Juan County	
(VAN (ST. 70)			whether DR, RKB, RT, GR		(2.15)	
		11. Elevation (Show)	6985' GR	, c.c.)		
	12 Chook Ar	proprieto Pov to l	Indicate Nature of Not	tian Donart or Otl	har Data	
	. 12. Check Ap	opropriate box to i	indicate Nature of Not	lice, Report of Ou	ner Data	
err er i	NOTICE OF INT	TNTION TO	م منت آل المالية	SUBSEQUENT	ÑÊDADT AL	
	NOTICE OF INT		er "			
		PLUG AND ABANDO			☐ ALTERING CASING ☐	
TEMPORARIL		CHANGE PLANS		E DRILLING OPNS.[] PANDA " []	
PULL OR ALT	ER CASING 🗌	MULTIPLE COMPL	☐ CASING/CEI	MENT JOB		
DOWNHOLE (COMMINGLE					
DOMINIOLE	JONIINITOLL					
DOWNIOLE						
OTHER:			OTHER:	COMPLETION REP	PORT	
OTHER:		ted operations. (Clear		COMPLETION REP		
OTHER:	be proposed or comple		rly state all pertinent detail	ls, and give pertinent	dates, including estimated date	
OTHER: 13. Descri	be proposed or comple		rly state all pertinent detail	ls, and give pertinent		
OTHER: 13. Descri	be proposed or comple		rly state all pertinent detail	ls, and give pertinent	dates, including estimated date	
OTHER: 13. Describe of start or reco	be proposed or comple ting any proposed worl mpletion.	x). SEE RULE 1103.	rly state all pertinent detail For Multiple Completions	ls, and give pertinent s: Attach wellbore d	dates, including estimated date iagram of proposed completion	
OTHER: 13. Descril of start or reco	be proposed or comple ting any proposed work impletion. RU Basin W/L. RIF	(c). SEE RULE 1103. H w/ 3 ³ / ₄ " gauge ring.	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs.	ls, and give pertinent s: Attach wellbore d	dates, including estimated date iagram of proposed completion	
OTHER: 13. Described of start or recommendation of the commendation of the commendati	be proposed or comple ting any proposed work impletion. RU Basin W/L. RIF Install Frac valve. P	A. SEE RULE 1103. H. w/ 3 3/4" gauge ring. T csg to 4500#/30min	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. . Test – OK.	ls, and give pertinent s: Attach wellbore d	dates, including estimated date iagram of proposed completion DW/L 6/7/10.	
OTHER: 13. Descril of start or reco	be proposed or completing any proposed work ompletion. RU Basin W/L. RIF Install Frac valve. P'RU W/L to Perf Pic	A. SEE RULE 1103. H. w/ 3 ¾" gauge ring. T csg to 4500#/30min tured Cliffs w/ .34" d	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. iam. – 2SFP @ 3890' – 38	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RD 884' = 12 Holes, 396	dates, including estimated date iagram of proposed completion D W/L 6/7/10. 3' = 2 Holes, 4032' – 4006' =	
OTHER: 13. Described of start or recommendation of the commendation of the commendati	be proposed or completing any proposed work ompletion. RU Basin W/L. RIF Install Frac valve. P' RU W/L to Perf Pict 52 Holes. Pictured 0	A w/3 ¾" gauge ring. T csg to 4500#/30min tured Cliffs w/ .34" d Cliffs Total Holes = 6	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. liam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15%	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RD 384' = 12 Holes, 3960 HCL. Frac w/ 14,16	dates, including estimated date iagram of proposed completion DW/L 6/7/10.	
OTHER: 13. Described of start or recommend of the start or recommend of the start	be proposed or completing any proposed work impletion. RU Basin W/L. RII Install Frac valve. P' RU W/L to Perf Pict 52 Holes. Pictured 0 pad w/ 100,900# of	A w/3 ³ / ₄ " gauge ring. T csg to 4500#/30min tured Cliffs w/ .34" d Cliffs Total Holes = 6020/40 Arizona Sand. 1	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. iam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback.	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' – 4006' = 62gals 70% Linear Gel 20#	
OTHER: 13. Described of start or recommendation of the commendation of the commendati	be proposed or completing any proposed work impletion. RU Basin W/L. RII Install Frac valve. P' RU W/L to Perf Pict 52 Holes. Pictured 0 pad w/ 100,900# of	A w/3 ³ / ₄ " gauge ring. T csg to 4500#/30min tured Cliffs w/ .34" d Cliffs Total Holes = 6020/40 Arizona Sand. 1	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. liam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15%	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback.	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' - 4006' = 62gals 70% Linear Gel 20# RCVD OCT 21'10	
OTHER: 13. Described of start or recommend of the start or recommend of the start	be proposed or completing any proposed working any proposed working the proposed working the proposed working the proposed with the proposed of the proposed of the proposed with the proposed of the proposed	A w/ 3 ³ / ₄ " gauge ring. T csg to 4500#/30min tured Cliffs w/ .34" d Cliffs Total Holes = 6020/40 Arizona Sand. N 3690'. Set CBP @ 361D WH. NU BOPE.	Run GR/CNL/CBL Logs. Test – OK. Iiam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback. c Equip.	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' – 4006' = 62gals 70% Linear Gel 20# RCUD OCT 21'10 OIL CONS. DIV.	
OTHER: 13. Descrit of start or record of 100 of 10	be proposed or completing any proposed working any proposed working the proposed working the proposed working the proposed with the proposed of the proposed of the proposed with the proposed of the proposed	A w/ 3 ³ / ₄ " gauge ring. T csg to 4500#/30min tured Cliffs w/ .34" d Cliffs Total Holes = 6020/40 Arizona Sand. N 3690'. Set CBP @ 361D WH. NU BOPE.	Run GR/CNL/CBL Logs. Test – OK. Iiam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback. c Equip.	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' – 4006' = 62gals 70% Linear Gel 20# RCUD OCT 21'10 OIL CONS. DIV.	
OTHER: 13. Descrit of start or record of 10/07/2010 09/10/2010 09/13/2010 09/17/2010 10/02/2010	be proposed or completing any proposed working any proposed working any proposed working any proposed working and W/L. RIF Install Frac valve. P'RU W/L to Perf Pict 52 Holes. Pictured opad w/ 100,900# of RIH w/ CBP set @ 3 MIRU AWS 266. NPT BOPE. Test – Ol	A w/ 3 ¾" gauge ring. T csg to 4500#/30min tured Cliffs w/ .34" d Cliffs Total Holes = 60 20/40 Arizona Sand. N 3690'. Set CBP @ 36 ID WH. NU BOPE. K. Tag CBP set @ 36	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. iam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback. c Equip.	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' – 4006' = 62gals 70% Linear Gel 20# RCUD OCT 21'10 OIL CONS. DIV.	
OTHER: 13. Descrit of start or record of 13. Descrit of 13. Descr	be proposed or completing any proposed working any proposed working any proposed working any proposed working and W/L. RIF Install Frac valve. P'RU W/L to Perf Pict 52 Holes. Pictured 6 pad w/ 100,900# of RIH w/ CBP set @ 3 MIRU AWS 266. NPT BOPE. Test – OI C/O to PBTD @ 41	A w/ 3 ¾" gauge ring. T csg to 4500#/30min tured Cliffs w/ .34" d Cliffs Total Holes = 60 20/40 Arizona Sand. N 3690'. Set CBP @ 36 ID WH. NU BOPE. K. Tag CBP set @ 36	Run GR/CNL/CBL Logs. Test – OK. Iiam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback. c Equip.	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' – 4006' = 62gals 70% Linear Gel 20# RCUD OCT 21'10 OIL CONS. DIV.	
OTHER: 13. Descrit of start or record or re	be proposed or completing any proposed working any proposed working any proposed working any proposed working and W/L. RIF Install Frac valve. P'RU W/L to Perf Pict 52 Holes. Pictured pad w/ 100,900# of RIH w/ CBP set @ 3 MIRU AWS 266. NPT BOPE. Test – OI C/O to PBTD @ 41' Flow Test PC.	A w/ 3 ¾" gauge ring. T csg to 4500#/30min tured Cliffs w/ .34" d Cliffs Total Holes = 60 20/40 Arizona Sand. 1 3690'. Set CBP @ 36 ID WH. NU BOPE. K. Tag CBP set @ 36 79'.	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. liam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo 74'. RD Flowback & Frac	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback. 6 Equip. CBP @ 3690'. Flowb	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' - 4006' = 62gals 70% Linear Gel 20# RCVD OCT 21'10 OIL CONS. DIV. pack. DIST. 3	
OTHER: 13. Descrit of start or record of 13. Descrit of 13. Descr	be proposed or completing any proposed working any proposed working any proposed working any proposed working and w. R. R. P. R. P.	A w/ 3 ¾" gauge ring. T csg to 4500#/30min tured Cliffs w/ .34" d Cliffs Total Holes = 60 20/40 Arizona Sand. 1 3690'. Set CBP @ 36 ID WH. NU BOPE. K. Tag CBP set @ 36 79'.	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. liam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo 74'. RD Flowback & Frac	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback. 6 Equip. CBP @ 3690'. Flowb	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' – 4006' = 62gals 70% Linear Gel 20# RCUD OCT 21'10 OIL CONS. DIV.	
OTHER: 13. Descrit of start or record or re	be proposed or completing any proposed working any proposed working any proposed working any proposed working and W/L. RIF Install Frac valve. P'RU W/L to Perf Pict 52 Holes. Pictured pad w/ 100,900# of RIH w/ CBP set @ 3 MIRU AWS 266. NPT BOPE. Test – OI C/O to PBTD @ 41' Flow Test PC.	A w/ 3 ¾" gauge ring. T csg to 4500#/30min tured Cliffs w/ .34" d Cliffs Total Holes = 60 20/40 Arizona Sand. 1 3690'. Set CBP @ 36 ID WH. NU BOPE. K. Tag CBP set @ 36 79'.	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. liam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo 74'. RD Flowback & Frac	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback. 6 Equip. CBP @ 3690'. Flowb	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' - 4006' = 62gals 70% Linear Gel 20# RCVD OCT 21'10 OIL CONS. DIV. pack. DIST. 3	
OTHER: 13. Descrit of start or record or record of start or record of start or record or	be proposed or completing any proposed working any proposed working any proposed working any proposed working and w. R. R. P. R. W. W. L. to Perf Pict 52 Holes. Pictured 6 pad w/ 100,900# of RIH w/ CBP set @ 3 MIRU AWS 266. N. PT BOPE. Test — OI C/O to PBTD @ 417 Flow Test PC. RIH w/ 132jts, 2 3/8 10/9/10.	A w/3 ¾" gauge ring. T csg to 4500#/30min tured Cliffs w/.34" d Cliffs Total Holes = 60 20/40 Arizona Sand. N 3690'. Set CBP @ 36 ID WH. NU BOPE. K. Tag CBP set @ 36 79'. ", 4.7#, J-55 tbg set @	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. liam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo 74'. RD Flowback & Frac 673' & D/O. CO & M/O C	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback. 6 Equip. CBP @ 3690'. Flowb	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' - 4006' = 62gals 70% Linear Gel 20# RCVD OCT 21'10 OIL CONS. DIV. pack. DIST. 3	
OTHER: 13. Descrit of start or record or re	be proposed or completing any proposed working any proposed working any proposed working any proposed working and w. R. R. P. R. P.	A w/3 ¾" gauge ring. T csg to 4500#/30min tured Cliffs w/.34" d Cliffs Total Holes = 60 20/40 Arizona Sand. N 3690'. Set CBP @ 36 ID WH. NU BOPE. K. Tag CBP set @ 36 79'. ", 4.7#, J-55 tbg set @	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. liam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo 74'. RD Flowback & Frac	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback. 6 Equip. CBP @ 3690'. Flowb	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' - 4006' = 62gals 70% Linear Gel 20# RCVD OCT 21'10 OIL CONS. DIV. pack. DIST. 3	
OTHER: 13. Descrit of start or record or record of start or record of start or record or record of start or record or record of start or record or re	be proposed or completing any proposed working any proposed working any proposed working any proposed working and w. R. R. P. R. W. W. L. to Perf Pict 52 Holes. Pictured 6 pad w/ 100,900# of RIH w/ CBP set @ 3 MIRU AWS 266. N. PT BOPE. Test — OI C/O to PBTD @ 417 Flow Test PC. RIH w/ 132jts, 2 3/8 10/9/10.	A w/3 ¾" gauge ring. T csg to 4500#/30min tured Cliffs w/.34" d Cliffs Total Holes = 60 20/40 Arizona Sand. N 3690'. Set CBP @ 36 ID WH. NU BOPE. K. Tag CBP set @ 36 79'. ", 4.7#, J-55 tbg set @	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. liam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo 74'. RD Flowback & Frac 673' & D/O. CO & M/O C	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback. 6 Equip. CBP @ 3690'. Flowb	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' - 4006' = 62gals 70% Linear Gel 20# RCVD OCT 21'10 OIL CONS. DIV. pack. DIST. 3	
OTHER: 13. Descrit of start or record or record of start or record or	be proposed or completing any proposed working any proposed working any proposed working any proposed working and w. R. R. P. R. W. W. L. to Perf Pict 52 Holes. Pictured opad w. 100,900# of RIH w. CBP set @ 3 MIRU AWS 266. N. PT BOPE. Test — OI C. C. Test D. C. RIH w. 132 jts, 2 3/8 10/9/10.	A w/ 3 ¾" gauge ring. T csg to 4500#/30min tured Cliffs w/ .34" d Cliffs Total Holes = 6020/40 Arizona Sand. Na G690'. Set CBP @ 36 ID WH. NU BOPE. K. Tag CBP set @ 3679'. Tag CBP set @ 3679'.	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. liam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo 74'. RD Flowback & Frac 673' & D/O. CO & M/O C	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback. 6 Equip. CBP @ 3690'. Flowb 60'. ND BOPE. NU	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' - 4006' = 62gals 70% Linear Gel 20# RCVD OCT 21'10 OIL CONS. DIV. pack. DIST. 3	
OTHER: 13. Descrit of start or record	be proposed or completing any proposed working any proposed working any proposed working any proposed working and w. R.	A w/3 ¾" gauge ring. T csg to 4500#/30min tured Cliffs w/ .34" d Cliffs Total Holes = 60 20/40 Arizona Sand. N 3690'. Set CBP @ 36 ID WH. NU BOPE. K. Tag CBP set @ 36 79'. Tag CBP set @ 36 Tag CBP set @ 36 Tag CBP set @ 36	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. liam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo 74'. RD Flowback & Frac 673' & D/O. CO & M/O C	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback. 6 Equip. CBP @ 3690'. Flowb 60'. ND BOPE. NU 05/21/2010 wledge and belief.	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' - 4006' = 62gals 70% Linear Gel 20# RCVD OCT 21'10 OIL CONS. DIV. back. DIST. 3 WH. RD RR @ 18:00hrs on	
OTHER: 13. Descrit of start or record	be proposed or completing any proposed working any proposed working any proposed working any proposed working and w. R.	A w/3 ¾" gauge ring. T csg to 4500#/30min tured Cliffs w/ .34" d Cliffs Total Holes = 60 20/40 Arizona Sand. N 3690'. Set CBP @ 36 ID WH. NU BOPE. K. Tag CBP set @ 36 79'. Tag CBP set @ 36 Tag CBP set @ 36 Tag CBP set @ 36	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. liam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo 74'. RD Flowback & Frac 673' & D/O. CO & M/O C @ 4091' w/ F-Nipple @ 40 Rig Released Date:	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback. 6 Equip. CBP @ 3690'. Flowb 60'. ND BOPE. NU 05/21/2010 wledge and belief.	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' - 4006' = 62gals 70% Linear Gel 20# RCVD OCT 21'10 OIL CONS. DIV. back. DIST. 3 WH. RD RR @ 18:00hrs on	
OTHER: 13. Descrit of start or record	be proposed or completing any proposed working any proposed working any proposed working any proposed working and w. R. R. P. R. W. W. L. to Perf Pict 52 Holes. Pictured opad w. 100,900# of RIH w. CBP set @ 3 MIRU AWS 266. N. PT BOPE. Test — OI C. C. Test D. C. RIH w. 132 jts, 2 3/8 10/9/10.	A w/3 ¾" gauge ring. T csg to 4500#/30min tured Cliffs w/ .34" d Cliffs Total Holes = 60 20/40 Arizona Sand. N 3690'. Set CBP @ 36 ID WH. NU BOPE. K. Tag CBP set @ 36 79'. Tag CBP set @ 36 Tag CBP set @ 36 Tag CBP set @ 36	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. liam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo 74'. RD Flowback & Frac 673' & D/O. CO & M/O C	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback. 6 Equip. CBP @ 3690'. Flowb 60'. ND BOPE. NU 05/21/2010 wledge and belief.	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' - 4006' = 62gals 70% Linear Gel 20# RCVD OCT 21'10 OIL CONS. DIV. pack. DIST. 3	
OTHER: 13. Descrit of start or record or record of start or record or record of start or record	be proposed or completing any proposed working and w. R.	A w/3 3/4" gauge ring. T csg to 4500#/30min tured Cliffs w/.34" d Cliffs Total Holes = 60 20/40 Arizona Sand. N 3690'. Set CBP @ 36 ND WH. NU BOPE. K. Tag CBP set @ 36 79'. Tag CBP set @ 36 Toy'.	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. liam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo 74'. RD Flowback & Frac 673' & D/O. CO & M/O C Rig Released Date: lete to the best of my know TITLE Staff Regul	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback. 6 Equip. CBP @ 3690'. Flowb 160'. ND BOPE. NU 105/21/2010 Wledge and belief.	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' - 4006' = 62gals 70% Linear Gel 20# RCVD OCT 21'10 OIL CONS. DIV. Dack. DIST. 3 WH. RD RR @ 18:00hrs on	
OTHER: 13. Descrit of start or record of start of start or record of start of start or record or record of start or record or record of start or record or	be proposed or completing any proposed working and w. R.	A w/3 ¾" gauge ring. T csg to 4500#/30min tured Cliffs w/ .34" d Cliffs Total Holes = 60 20/40 Arizona Sand. N 3690'. Set CBP @ 36 ID WH. NU BOPE. K. Tag CBP set @ 36 79'. Tag CBP set @ 36 Tag CBP set @ 36 Tag CBP set @ 36	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. iam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo 74'. RD Flowback & Frac i73' & D/O. CO & M/O C Rig Released Date: lete to the best of my know TITLE Staff Regul	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback. 6 Equip. CBP @ 3690'. Flowb 60'. ND BOPE. NU 05/21/2010 vledge and belief.	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' – 4006' = 62gals 70% Linear Gel 20# RCVD OCT 21'10 OIL CONS. DIV. back. DIST. 3 WH. RD RR @ 18:00hrs on	
OTHER: 13. Descrit of start or record of start of start or record of start of start or record o	be proposed or completing any proposed working and w. R.	A w/3 ¾" gauge ring. T csg to 4500#/30min tured Cliffs w/.34" d Cliffs Total Holes = 60 20/40 Arizona Sand. N 3690'. Set CBP @ 36 ID WH. NU BOPE. K. Tag CBP set @ 36 79'. The set and comp ove is true and comp E-mail address:	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. liam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo 74'. RD Flowback & Frac 673' & D/O. CO & M/O C Rig Released Date: lete to the best of my know TITLE Staff Regul crystal.tafoya@cc	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback. 6 Equip. CBP @ 3690'. Flowb 160'. ND BOPE. NU 105/21/2010 wledge and belief. State of the component of the	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' – 4006' = 62gals 70% Linear Gel 20# RCUD OCT 21'10 OIL CONS. DIV. back. DIST. 3 WH. RD RR @ 18:00hrs on DATE 10/20/10 PHONE: 505-326-9837 OT,	
OTHER: 13. Descrit of start or record of start of start or record of start of start or record o	be proposed or completing any proposed working and w. R.	A w/3 ¾" gauge ring. T csg to 4500#/30min tured Cliffs w/.34" d Cliffs Total Holes = 60 20/40 Arizona Sand. N 3690'. Set CBP @ 36 ID WH. NU BOPE. K. Tag CBP set @ 36 79'. The set and comp ove is true and comp E-mail address:	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. liam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo 74'. RD Flowback & Frac 673' & D/O. CO & M/O C Rig Released Date: Crystal.tafoya@cc Deputy Oil	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback. 6 Equip. CBP @ 3690'. Flowb 160'. ND BOPE. NU 105/21/2010 Wledge and belief.	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' – 4006' = 62gals 70% Linear Gel 20# RCUD OCT 21'10 OIL CONS. DIV. back. DIST. 3 WH. RD RR @ 18:00hrs on DATE 10/20/10 PHONE: 505-326-9837 OT,	
OTHER: 13. Descrit of start or record of start of start or record of start of start or record o	be proposed or completing any proposed working and w. R.	A w/3 ¾" gauge ring. T csg to 4500#/30min tured Cliffs w/.34" d Cliffs Total Holes = 60 20/40 Arizona Sand. N 3690'. Set CBP @ 36 ID WH. NU BOPE. K. Tag CBP set @ 36 79'. The set and comp ove is true and comp E-mail address:	rly state all pertinent detail For Multiple Completions Run GR/CNL/CBL Logs. Test – OK. liam. – 2SFP @ 3890' – 38 6. Acidize w/ 10bbls 15% N2:614,000SCF. Start Flo 74'. RD Flowback & Frac 673' & D/O. CO & M/O C Rig Released Date: lete to the best of my know TITLE Staff Regul crystal.tafoya@cc	Is, and give pertinent s: Attach wellbore d TOC @ Surface. RE 884' = 12 Holes, 396: 6 HCL. Frac w/ 14,16 wback. 6 Equip. CBP @ 3690'. Flowb 160'. ND BOPE. NU 105/21/2010 wledge and belief. State of the component of the	dates, including estimated date iagram of proposed completion O W/L 6/7/10. 3' = 2 Holes, 4032' – 4006' = 62gals 70% Linear Gel 20# RCVD OCT 21'10 OIL CONS. DIV. back. DIST. 3 WH. RD RR @ 18:00hrs on	