

RECEIVED

AUG 11 2010

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Farmington Field Office
Bureau of Land Management

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator
BURLINGTON
RESOURCES OIL & GAS COMPANY LP

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

Surf: Unit H (SENE), 1750' FNL & 800' FEL, Section 15, T27N, R6W, NMPM

5. Lease Number
SF-079365
6. If Indian, All. or
Tribe Name
7. Unit Agreement Name
San Juan 28-6 Unit
8. Well Name & Number
San Juan 28-6 Unit 209
9. API Well No.
30-039-20845
10. Field and Pool
11. Basin Dakota
County and State
Rio Arriba Co., NM



12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☐ Notice of Intent

☐ Abandonment

☐ Change of Plans

☒ Other

☐ Cathodic Protection

☒ Subsequent Report

☐ Recompletion

☐ New Construction

☐ Plugging

☐ Non-Routine Fracturing

☐ Final Abandonment

☐ Casing Repair

☐ Water Shut off

☐ Altering Casing

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

Attached is a drawing of the placement of the cathodic ground bed, rectifier and cable for the subject well.

14. I hereby certify that the foregoing is true and correct.

Signed Brandie Blakley Brandie Blakley Title Staff Regulatory Technician Date 8-11-10

(This space for Federal or State Office use)

APPROVED BY [Signature] Title Per. Eng. Date 8/10/10

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.


NMOCD

pc



San Juan 28-6 Unit 27 & 209

Section 15, T27N, R6W, N.M.P.M., Rio Arriba County, NM



Drill new ground bed approximately 154' North West of #27 wellhead at staked location. Run new positive cable from existing rectifier to new ground bed at length listed below, and repair negative to wellhead.

Positive: 15'

Total Ditch: 15'

By: Steven Gillette
Date: 5/25/10