Torm 3160-5 (August 2007)

# UNITED STATES DEPARTMENT OF THE INTERIOR APR

APR 05 2011

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No. NMSF 078879

6. If Indian, Allottee or Tribe Name

BUREAU OF LAND MANAGEMENT armington Field Office
SUNDRY NOTICES AND REPORTS ON WELLS and Management of the proposals to drill or to re-enter an analysis of the proposals.

	form for proposals to d Use Form 3160-3 (APD				o. If Mulail, Anotice	of Tribe (value	
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.  Canyon Largo Unit		
1. Type of Well  Oil Well  Gas Well  Other				8. Well Name and No. Canyon Largo Unit #99 <b>400</b>			
2. Name of Operator Huntingotn Energy, L.L.C.					9. API Well No. 30-039-30810		
3a. Address 908 N.W. 71st St. Oklahoma City, OK 73116				nclude area code) 10. Field and Pool of Basin Dakota		Exploratory Area	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) NWNW, Lot D, 1160' FNL & 890' FWL Sec. 24 T25N-R7W					11. Country or Parish, State Rio Arriba Co., NM		
12. CHEC	CK THE APPROPRIATE BOX(E	S) TO INDICA	TE NATURE	OF NOTIC	E, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTI					ION	
Notice of Intent	Acidize Alter Casing Casing Repair	Deepen Fracture		Recla	nction (Start/Resume) mation	Water Shut-Off  Well Integrity  Other Completion	
✓ Subsequent Report	Change Plans	Plug and	Abandon	Temp	orarily Abandon	- John T	
Final Abandonment Notice	Convert to Injection	Plug Bacl	K	Water	r Disposal		
determined that the site is ready for Please see attachment for work	performed on the above refer	RECEASE OF THE PARTY OF THE PAR	ENED AND DIST.	18 18 20 21 22 23 24 24 24 24 24 24 24 24 24 24 24 24 24		ED FOR RECORD  O 7 2011  TON FIELD OFFICE	
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Catherine Smith			Title Regulatory				
Signature Catherine	hmtZ	Da	te 04/04/201	1			
	THIS SPACE FO	R FEDERA	L OR STA	TE OFF	ICE USE		
Approved by			Title			Data	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.					1	Date	
Title 18 U.S.C. Section 1001 and Title 43 fictitious or fraudulent statements or repre			knowingly and	l willfully to	make to any departmen	t or agency of the United States any false,	

# Huntington Energy, L.L.C.

908 NW 71<sup>st</sup> Street Oklahoma City, OK 73116 (405) 840-9876 & Fax # (405) 840-2011

## Canyon Largo Unit #499

NWNW, Sec 24-25N-7W Rio Arriba Co., New Mexico API: 30-039-30810

### COMPLETION SUNDRY ATTACHMENT:

3/17/11: DEWATER RESERVE PIT. JS TRUCKING AND RS TRUCKING. HAULING TO TNT ENVIRONMENTAL. PERMIT # NM-01-0008.

3/18/11: MIRU WELLHEAD. RU SCHLUMBERGER, RIH W/ 1 11/16" OD RST LOG. LOG BACK TO SURFACE. RD MO. MI HURRICANE WELL SERVICE ON MONDAY.

3/19/11: MEET MARK KELLY & CRAIG WILLEMS W/ BLM TO DISCUSS BATTERY PLACEMENT. BATTERY TO BE PLACED ON THE NORTH EAST CORNER OF LOCATION. ONSITE APPROVAL. ✓

3/21/11: MOVE IN HURRICANE. SPOT IN EQUIPMENT AND NU BOPS. RU PUMP AND PIT, PRESSURE TEST CSG TO 5000 PSI, TEST BLIND 250 PSI LOW, 5000 PSI HIGH, TEST PIPE RAMS 250 PSI LOW, 5000 PSI HIGH. SD FOR WIND.

3/22/11: SAFETY MEETING, RIG UP. STRAP TBG AND PICK UP BIT AND SCRAPPER AND RUN IN HOLE. TAG @ 7197', RIG UP POWER SWIVEL, CLEAN OUT FROM 7197-7346'. CIRC HOLE CLEAN, RIG DOWN SWIVEL, PULL 5 STANDS, SDFN.

DEWATER RESERVE @ 16 LOADS HAULED TO TNT ENVIRONMENTAL LANDFILL @ 19/BBL.

3/23/11: SAFETY MEETING, TOOH LAY DOWN BIT AND SCRAPER, RU SCHLUMBERGER. LOG HOLE FROM 7344-6800'. RIG DOWN LOGGERS. W/O BASIN WIRELINE. RIG UP BASIN AND PERF FROM 7293-7302', 18 HOLES, 9', 2 SPF, 7256-7260', 8 HOLES, 4', 2 SPF, 7234-7246', 24 HOLES, 12', 2 SPF, 7206-7209', 6 HOLES, 3', 2 SPF. RIG DOWN BASIN. SDFN.

3/29/11: RU STINGER TREESAVER & HALLIBURTON. PUMP 1000 GALS 15% FE ACID. FRAC LOWER DAKOTA: 28,000 GAL DELTA 15 FOAM 70% N2.

3/30/11: RIG UP BASIN WIRELINE, RUN IN HOLE W/GAUGE RING TO 7195'. RUN IN AND SET HALLIBURTON FRAC PLUG @ 7195'. PRESSURE TEST PLUG TO 4000 PSI, HELD. PERF 7180-7192', 7149-7164', 7140-7146'. 7133-7138', 7108-7120', 7065-7071', 7000-7023', 2 SPF, TOTAL OF 158 HOLES. ✓

RU STINGER TREESAVER & HALLIBURTON. PUMP 1000 GALS 15% FE ACID. FRAC UPPER DAKOTA AS FOLLOWS: 58,000 GAL DELTA 200 W/ ACTIVATOR.

#### 3/31/11

FLOWING @ 600 PSI ON 28/64" CHOKE. PREP TO RIH & DRILL PLUG & LAND TBG.

4/1/11: RIG UP PUMP AND LINES. MAKE UP BIT AND PUMP OFF SUB, PUMP 30 BBLS TO KILL WELL. TIH W/ BIT, PUMP OFF SUB, 1 JT, SN, 224 JTS TAG @ 7195°. RIG UP POWER SWIVEL, DRLG FRAC PLUG, TAG @ 7285° CLEAN OUT TO 7345°(PBTD). CIRC HOLE CLEAN LAY DOWN 5 JTS, LAND TBG @ 7210′ KB. 224 JTS OF 2¾″ 4.7# J-55 TBG IN HOLE. TBG STRING PUMP OFF SUB, 1 JT, SN @ 7177′, 223 JTS. NIPPLE DOWN BOP, NIPPLE UP WELLHEAD AND PUMP OFF BIT 2800 PSI TO PUMP OFF. RIG UP SWAB EQUIPMENT. SWAB BACK 80 BBLS, WELL FLOWING. ✓

4/2/11: CONTINUE WITH 24 HR FLOW TEST. ✓