submitted in lieu of Form 3160-5

RECEIVED

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

MAR 29 2011

**************************************		migration Field Office
Sundry Notices and Reports on Wells	Little	au of i and Managament
1. Type of Well GAS	5. 6.	Lease Number SF-078312 If Indian, All. or Tribe Name
2. Name of Operator	7.	Unit Agreement Name
BURLINGTON RESOURCES OIL & GAS COMPANY LP	8.	Well Name & Number
3. Address & Phone No. of Operator	· · · · · · · · · · · · · · · · · · ·	Hubbard 100
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No.
4. Location of Well, Footage, Sec., T, R, M		30-045-30884
Unit M (SWSW), 735' FSL & 730' FWL, Section 11, T32N, R12W, NMPM	10.	Field and Pool Basin Fruitland Coal
	11.	County and State San Juan, NM
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT	r, other	DATA
Type of Submission Notice of Intent Notice of Intent Abandonment Recompletion Non-Routine Fracturi Casing Repair Final Abandonment Altering Casing Conversion to Injectice	ng	Other - Tubing
Notice of Intent Abandonment Recompletion New Construction Non-Routine Fracturi Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations	ng on	
Notice of Intent Abandonment Recompletion New Construction Non-Routine Fracturi Casing Repair Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 03/15/2011 MIRU DWS 29. ND WH. NU BOPE. PT BOPE. Test - OK. Remove tbg hange to PBTD @ 2569'. RIH w/ 77jts, 2 3/8", 4.7#, J-55 tbg set @ 2446' (New set depth) w/ F-N	on er. POOh w/	2 3/8" tbg. Circ. clean. C/
Notice of Intent Abandonment Recompletion New Construction Non-Routine Fracturi Casing Repair Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 03/15/2011 MIRU DWS 29. ND WH. NU BOPE. PT BOPE. Test - OK. Remove tbg hange to PBTD @ 2569'. RIH w/ 77jts, 2 3/8", 4.7#, J-55 tbg set @ 2446' (New set depth) w/ F-N	on er. POOh w/	2 3/8" tbg. Circ. clean. C/
Notice of Intent Abandonment Change of Plans Recompletion New Construction X Subsequent Report Plugging Non-Routine Fracturi Casing Repair Water Shut off	er. POOh w/ipple @ 244	2 3/8" tbg. Circ. clean. C/5'. ND BOPE. NU WH. R DIST. 3 DIL CONS. DIV. RCVD APR 5 '11

ASSEPTED FOR FECORE

MAR 3 1 2011

PAFAMIGTON FIELD OFFICE



PL