Form 3160-5- (August 1999)

UNITED S DEPARTMENT OF BUREAU OF LAND

STATES	4	FORM
THE INTERIOR	/	OMB N
	/	Expires: No
MANAGEMENT		<u> </u>

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 200

Expires:	November	30,	2000	
Lease Serial No				
NIMMIMOS701				

0
1
Λ
U

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use thi abandoned wel	s form for proposals to di I. Use form 3160-3 (APD)	rill or to re-e for such pro	nter an oposals.		6. If Indi	an, Allottee or	Tribe Name
SUBMIT IN TRI	PLICATE - Other instruction	ons on reve	se side.	1	7. If Uni	t or CA/Agreen	nent, Name and/or No.
1. Type of Well ☐ Oil Well ☐ Gas Well ☐ Oth						ame and No. IAM B 6	
Name of Operator CONOCO INC	Contact: DI E-	EBORAH MA Mail: deborah.	RBERRY marberry@c	onocophillips	9. API W .com 30-04	⁷ ell No. 15-20360-0 0	-S1
3a. Address PO BOX 2197, DU 3084 HOUSTON, TX 77252-2197	11	3b. Phone No. (Ph: 832.486. Fx: 832.486.2	2326	code)	10. Field SOU	and Pool, or E TH BLANCO	xploratory) PICTURED CLIFFS
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)				11. Cour	nty or Parish, an	nd State
Sec 3 T27N R8W SESW 0850 36.59830 N Lat, 107.67159 W	DFSL 1600FWL / Lon				SAN	JUAN COU	NTY, NM
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE I	NATURE (OF NOTICE	, REPORT,	OR OTHER	DATA
TYPE OF SUBMISSION			TYP	E OF ACTIO	N		
□ Notice of Intent	☐ Acidize	□ Deepe	n	□ Pro	duction (Start	Resume)	☐ Water Shut-Off
_	☐ Alter Casing	□ Fractu	re Treat	□ Rec	lamation		☐ Well Integrity
Subsequent Report Subsequent Re	Casing Repair	_	Construction		omplete		Other
Final Abandonment Notice	☐ Change Plans	_	ind Abando		nporarily Aba	ndon	
	Convert to Injection	□ Plug l	Back	□ Wa	ter Disposal		
testing has been completed. Final A determined that the site is ready for I In response to letter dated 12 The above mentioned well ha	inal inspection.) /11/02 - NMNM-05791 (WC) s been plugged and aband	C) 3162.3-4 (7	7100).		mary.	1500712727 10071272727	28 29 30 3 1 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
14. Thereby certify that the foregoing i	Electronic Submission #1	OCO INC. ser	it to the Far	mington		SE)	
Name (Printed/Typed) DEBORA	•			BMITTING (
Signature (Electronic	Submission)		Date 12 /	18/2002			
	THIS SPACE FO	R FEDERAI	OR STA	TE OFFIC	E USE		
Approved By ACCEPT	ED			HEN MASO OLEUM EN			Date 12/19/2002
Conditions of approval, if any, are attach certify that the applicant holds legal or ec which would entitle the applicant to conditions.	uitable title to those rights in the luct operations thereon.	subject lease	Office Far				
Title 18 U.S.C. Section 1001 and Title 4. States any false, fictitious or fraudulent	3 U.S.C. Section 1212, make it a castatements or representations as t	crime for any pe to any matter wi	rson knowing thin its jurisd	ly and willfully iction.	to make to any	department or	agency of the United

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 * fax: 505-325-1211

ConocoPhillips Inc.

November 8, 2002

Graham B WN Federal #6

Page 1 of 1

850' FSL & 1600' FWL, Section 3, T-27-N, R-8-W San Juan County, NM

Plug & Abandonment Report

Lease Number: NM-05791 API Number: 30-045-20360

Cementing Summary:

Plug #1 with retainer at 2012', spot 24 sxs cement inside 4-1/2" casing above retainer up to 1702' to isolate Pictured Cliffs perforations and to cover the Fruitland top.

Plug #2 with 24 sxs cement inside 4-1/2" casing from 1357' to 1047' to cover Kirtland and Ojo Alamo tops.

Plug #3 with 32 sxs cement inside 4-1/2" casing from 246' to surface, circulate good cement out casing valve.

Plugging Summary:

Notified BLM on 11/5/02

- 11-05-02 MOL. Held JSA. RU. Lay relief line to pit. Blow well down from 60# to 20#. Pump 25 bbls of water down tubing to kill well. ND wellhead and NU BOP. Test BOP. TOH and tally 67 joints 2-3/8" EUE tubing, total 2066'. Round trip 4-1/2" casing scraper to 2036'. Shut in well. SDFD.
- 11-06-02 Safety Meeting. Blow down 50# casing pressure and pressure test bradenhead to 300# with ½ bbl of water for 5 minutes, held OK. Calculate TOC in annulus at 12'. TIH and set 4-1/2 DHS cement retainer at 2012'. Pressure test tubing to 1000#. Circulate well clean with 40 bbls of water. Pressure test casing to 500# for 5 minutes, held OK. Plug #1 with retainer at 2012', spot 24 sxs cement inside 4-1/2" casing above retainer up to 1702' to isolate Pictured Cliffs perforations and to cover the Fruitland top. PUH to 1357'. Plug #2 with 24 sxs cement inside 4-1/2" casing from 1357' to 1047' to cover Kirtland and Ojo Alamo tops. PUH to 246'. Plug #3 with 32 sxs cement inside 4-1/2" casing from 246' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut in well and WOC. RD. Cut off wellhead and found cement down 10' in casing. Mix 36 sxs cement to fill casing and annulus and then install P&A marker. MOL.

V. Lucero and D. Benallie, BLM representatives, were on location.