


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Monica D. Johnson
Address	5525 Hwy. 64, Farmington, NM 87401	Telephone No.	505-599-3458
Facility Name	AXI Apache N #16	Facility Type	Producing Gas Well
Surface Owner	Jicarilla Tribe	Mineral Owner	Jicarilla Tribe
		Lease No.	Jic 121

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	12	T25N	R4W	1500'	South	850'	West	Rio Arriba

Latitude 36.4109466° Longitude 107.2098235°

NATURE OF RELEASE

Type of Release – Condensate	Volume of Release – 120 BBL	Volume Recovered – 15 BBL
Source of Release: Frozen tank valve	Date and Hour of Occurrence 12/12/05	Date and Hour of Discovery 12/12/05 – 9:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust – OCD – via email Jicarilla EPO – Dixon Sandoval – via phone & fax Jicarilla Oil & Gas Admin. – Rod Velarde via phone & Fred Vigil via fax	
By Whom? Monica D. Johnson	Date and Hour – 12/13/05 – 11:00 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **A spill of 120 BBL condensate was discovered at the AXI Apache N #16 at approximately 9:00 a.m. on 12/12/05, due to a valve on the 400 BBL condensate tank freezing and breaking. All spilled fluids remained within the bermed area, and a vacuum truck was immediately called to recover the spilled fluids, of which 15 BBL were recovered. Both the sales and drain valves on the condensate tank were replaced with non-freeze type valves.**

Describe Area Affected and Cleanup Action Taken.* **All spilled fluids remained within the bermed area and 15 BBL were recovered by vacuum truck. A work order has been submitted for remediation, where any stained soils encountered will be excavated and hauled to TNT Landfarm and the excavated area will be backfilled with clean fill dirt.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Monica D. Johnson</i>	OIL CONSERVATION DIVISION	
Printed Name: Monica D. Johnson	Approved by District Supervisor: <i>Denny Foust</i> for Charlie Perera	
Title: Environmental Specialist	Approval Date: 9/19/05	Expiration Date:
E-mail Address: monica.johnson@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/13/05 Phone: 505-599-3458		

* Attach Additional Sheets If Necessary

1106F0535431008

✓



San Juan Operations
5525 Hwy. 64
Farmington, NM 87401

December 14, 2005

Mr. Dixon Sandoval
Jicarilla Environmental Protection Office
P.O. Box 507
Dulce, NM 87528

RE: Spill Notification
AXI Apache N #16
Unit L, Section 12, T25N, R4W
Rio Arriba County, New Mexico
API #30-039-21983

Dear Mr. Sandoval,

Enclosed please find the Release Notification and Corrective Action Report for the recent 120 BBL condensate spill at the AXI Apache N #16.

A spill of 120 BBL condensate was discovered at the AXI Apache N #16 at approximately 9:00 a.m. on 12/12/05, due to a valve on the 400 BBL condensate tank freezing and breaking. All spilled fluids remained within the bermed area, and a vacuum truck was immediately called to recover the spilled fluids, of which 15 BBL were recovered. Both the sales and drain valves on the condensate tank were replaced with non-freeze type valves.

A work order has been submitted for remediation and one-call notifications have been made. Stained soils encountered will be excavated and hauled to TNT Landfarm and the excavated area will be backfilled with clean fill dirt. We will need an archaeologically cleared area to haul dirt from to fill the excavated area.

Should you have any questions or require additional information, please give me a call at 505-599-3458.

Sincerely,

Monica D. Johnson
Environmental Specialist

Cc: Jicarilla Oil & Gas Administration – Mr. Fred Vigil
Jicarilla Natural Resource Department – Mr. Joe McNeese
Jicarilla Agency Realty Office – Ms. Annette Torivio
New Mexico Oil Conservation Division (Aztec) – Mr. Denny Foust

