

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

30-045-28360

Name of Company Compressor Systems Inc.		Contact <input type="checkbox"/> Charles R. Viverette Jr.	<input checked="" type="checkbox"/> Initial Report <input checked="" type="checkbox"/> Final Report
Address P.O. Box 60760 Midland, Texas 79711-0760		Telephone No. <input type="checkbox"/> 432-495-3169	
Facility Name ConocoPhillip Co.'s SJ 32-7- 219 #2 Facility		Facility Type <input type="checkbox"/> natural gas compression	
Surface Owner Federal	Mineral Owner	Lease No. <input type="checkbox"/>	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	AS	31N	7W	800	North	800	West	San Juan

NATURE OF RELEASE

Type of Release Screw Compressor Oil	Volume of Release 250 Gallons	Volume Recovered <input type="checkbox"/> 20 Gallons
Source of Release Screw Compressor Front Seal	Date and Hour of Occurrence Unknown	Date and Hour of Discovery <input type="checkbox"/> Nov. 7, 2005 / 12:00 P.M.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? <input type="checkbox"/>	Date and Hour <input type="checkbox"/>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The front seal went out on the screw compressor. The seal or the complete compressor was replaced.		
Describe Area Affected and Cleanup Action Taken.* The spill appears to be primarily on the left side of the skid, running across the location. The remedial action was to clean up as much as possible ourselves and then schedule with Foutz & Bursome for the remainder. They will remove all contaminated soil and gravel and replace it with clean soil and gravel. The contaminated soil will be taken to Envirotech's local land farm.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: Charles R. Viverette Jr.	OIL CONSERVATION DIVISION	
Printed Name: Charles R. Viverette Jr.	Approved by <input type="checkbox"/> District Supervisor: Jerry Foutz for Charlie Perrin	
Title: Environmental Specialist I	Approval Date: 11/22/05 Expiration Date:	
Date: November 17, 2005 Phone: (432) 495-3169	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

NOG F0532630298