District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

\* Attach Additional Sheets If Necessary

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division, 1220 South St. Francis Dr. Santa Fe, NM 87505



Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action  30 045 11023 OPERATOR Separate Management Management Report Management Report Management Report Re															
						OPERA'				<u>M</u> Initia		X	Final Report		
Name of Co		Hurt O				Contact	Jo2 .	Buck	74	ndy Sai	Je				
Facility Nat			twy Hus	tia, TX 7874	Telephone No. 330-8577 / (512) Facility Type Production/ Injection										
Surface Owner Najajo Tribe Mineral Owner Hart Oil 4 Fas Lease No.															
	· · · · · · · · · · · · · · · · · · ·					OF REI									
Unit Letter							h/South Line   Feet from the   East/West Li								
0	3_	31N	B 17U	330 FSL	<i>}31</i>	OFEL					San Juan				
			Lat	itude	_ Longitud	e									
NATURE OF RELEASE															
Type of Rele		Produced	Nater			Volume of	Release	256	1/5		Recovered				
Source of Re		Date and Hour of Occurrence Date and Hour of Discovery 10/14/04 100													
Was Immediate Notice Given?  ☐ Yes ☐ No ☐ Not Required							If YES, To Whom?  Denny W/ OCD								
By Whom? Jon Buck							Date and Hour 10/14/04 1600								
Was a Watercourse Reached? 							olume <b>Im</b> q	pacting th	ne Wate	ercourse.					
If a Waterco	irse was Imr	nacted Descri	he Fully *			<u> </u>				<del></del>					
If a Watercourse was Impacted, Describe Fully.*															
Describe Cause of Problem and Remedial Action Taken.* Under ground injection line failed near the wellhead. Replaced tree, installed a ball check															
whole ground injection line taken near the wellnead. Replaced tree, installed a ball check															
value and 2 sts. of 2" line.															
Describe Area Affected and Cleanup Action Taken.*															
Berned location was floorled and a one fast will be 40 de la tail I'll															
Bermed location was flooded and a one foot wide by 40 yds long tail followed the road towards the main plant. The injection water scatted in before the hot															
oiler arrived.															
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and															
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability															
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health															
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.															
Maria, succe, or room farm man or regulations.							OIL CONSERVATION DIVISION								
s: 4															
Signature:						Approved by District Supervisor: for frank Chave >									
Printed Name: Non BOCK							, [								
Title: Pro	oduction	n Sop	erviso	<u>r</u>		Approval Dat	e: 11/1	19/0	β   I	Expiration I	Date:	· · · ·			
E-mail Addre	ess: Anna	bode 7 @	peopleA	L. com		Conditions of	Approva	1:			Attached	П			
	119/04		•	330-8577	,							_			

11 DEFOISINGS