


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form



Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Monica D. Olson
Address	5525 Hwy. 64, Farmington, NM 87401	Telephone No.	505-599-3458
Facility Name	San Juan 31-6 Unit #213	Facility Type	Producing Gas Well
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	NM-03404
		API # 30-039-24531	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	5	T30N	R6W	1865'	South	1595'	West	Rio Arriba

Latitude 36.83957° Longitude 107.4893°

NATURE OF RELEASE

Type of Release – Produced Water	Volume of Release – 15 BBL	Volume Recovered – 15 BBL
Source of Release: Tank overflow	Date and Hour of Occurrence 12/14/04	Date and Hour of Discovery 12/14/04 – 4:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust – OCD – via email Mark Kelly – BLM – discovered and notified via email	
By Whom? Monica Olson	Date and Hour – 12/16/04 – 10:00 a.m. via e-mail	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **A produced water spill of 15 BBL was discovered on Tuesday afternoon, 12/14/04 by Mark Kelly with the BLM. He informed ConocoPhillips that we had a tank running over. A vacuum truck was called to location at 4:40 PM and they picked up approximately 15 BBL of produced water. The spill was contained within the berm, affecting an area about 15' in diameter by 9" deep. The cause of the spill was an electrical problem that failed to start the water pump at the location. This problem has since been corrected.**

Describe Area Affected and Cleanup Action Taken.* **No water left the berm. All spilled fluids were recovered (15 BBL). The problem with the electrical system to the water pump was repaired. This will be the final report.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Monica D. Olson</i>	OIL CONSERVATION DIVISION	
Printed Name: Monica D. Olson	Approved by District Supervisor: <i>Denny Foust</i> <i>for Charlie Perrin Actg</i>	
Title: Safety, Health, Environmental, & Regulatory Technician	Approval Date: <i>12/27/04</i>	Expiration Date:
E-mail Address: monica.olson@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/16/04	Phone: 505-599-3458	

* Attach Additional Sheets If Necessary

N DGF 0436 236555