


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised June 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Burlington Resources	Contact	Gregg Wurtz
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	(505) 320-2653
Facility Name	NYE FEDERAL	Facility Type	Gas Well

Surface Owner	Fed	Mineral Owner	Fed	Lease No.	NMSF-078197
---------------	-----	---------------	-----	-----------	-------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	08	029N	010W	1830	North	1020	West	San Juan

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	30 BBLS.	Volume Recovered	28 BBLS.
Source of Release	Water pit tank	Date and Hour of Occurrence	10/16/2003 7:00:00 AM	Date and Hour of Discovery	10/16/2003 11:00:00 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust		
By Whom?	Gregg Wurtz	Date and Hour	10/16/2003 3:30:00 P		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully.\*  
None. Contained on location

Describe Cause of Problem and Remedial Action Taken.\*  
Well engineering problem. Well sanded up tubing and well was being produced off casing. Sand plugged casing also and water loaded casing and then unloaded an unusual large amount of water to the water pit tank. Engineer Dept. is looking into a solution to handle problem. In the interim a 286 bbl water tank was installed to prevent future overfills. Water was removed by vacume truck and soil was raked to promote rehabilitation of soils.

Describe Area Affected and Cleanup Action Taken.\*  
Area adjacent to the water pit tank confined in the excavation of the pit tank and within the containment berm of the storage tank.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gregg Wurtz</i>	OIL CONSERVATION DIVISION <i>Denny Foust</i> for Frank Chavez	
Printed Name: Gregg Wurtz	Approved by District Supervisor:	Expiration Date:
Title: Environmental Representative	Approval Date: 11/19/03	Attached <input type="checkbox"/>
E-mail Address: lhasely@br-inc. com or gwurtz@br-inc. com	Conditions of Approval:	
Date: 11-07-03	Phone: (505) 326-9841 or 9537	

\* Attach Additional Sheets If Necessary

n DCF0332854241