

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30039 20244

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	BP America Production Company	Contact	Brittany Benko
Address	200 Energy Court Farmington, NM 87401	Telephone No.	(505) 326-9235
Facility Name	Jicarilla Gas Com 35C #1	Facility Type	Wellsite

Surface Owner	Jicarilla Apache Tribe	Mineral Owner	Jicarilla Apache Tribe	Lease No.	30-039-20088
---------------	------------------------	---------------	------------------------	-----------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	2	24N	5W					San Juan County

NATURE OF RELEASE

Type of Release	Condensate	Volume of Release	6.6 bbls	Volume Recovered	0 bbls
Source of Release	Condensate Tank	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	August 5, 2003 9:20 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust		
By Whom?	Don Brooks	Date and Hour	August 6, 2003 9:15 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The Field Tech was performing his monthly site inspection and discovered a stain and small leak coming from inspection cover gasket on the condensate tank. He immediately called a truck and had the remaining fluid in the tank transferred to another tank.

Describe Area Affected and Cleanup Action Taken.*

The condensate was contained inside the berm. The contaminated soil will be cleaned up according to the direction of the Jicarilla EPO. It will be removed to the BP operated, Crouch Mesa Landfarm and testing around the tank will be completed to verify that the soil meets the Jicarilla EPO requirements, 100 ppm TPH, 10 ppm benzene and 50 ppm BTEX

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.


Signature: <i>Brittany D Benko</i>	OIL CONSERVATION DIVISION	
Printed Name: Brittany D Benko	Approved by District Supervisor: <i>Denny Foust</i> <i>For Frank Chavez</i>	
Title: Environmental Coordinator	Approval Date: 9/05/03	Expiration Date:
Date: 08/29/2003 Phone: (505) 326-9235	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

N DGF032253363

2

bp



BP America Production Company

200 Energy Court
Farmington, NM 87401

Phone: (505) 326-9200

August 29, 2003

Bureau of Land Management
435 Montano Road, NE
Albuquerque, NM 87107-4935
Attn: Pat Hester

RE: Release, Jicarilla Gas Com 35C #1, Unit M, Sec 2, T24N, R5W (API 30-039-20088)

Dear Ms. Hester,

This letter is being sent as a follow up written notification to the spill report made to you verbally on August 6, 2003 at 9:20 am on the Jicarilla Gas Com 35 C #1. The Field Tech was performing his monthly site inspection and discovered a stain and small leak coming from inspection cover gasket on the condensate tank. He immediately called a truck and had the remaining fluid in the tank transferred to another tank. The condensate was contained inside the berm and spilled amount was determined to be 6.6 barrels. The contaminated soil will be cleaned up according to the direction of the Jicarilla EPO. It will be removed to the BP operated, Crouch Mesa Landfarm and testing around the tank will be completed to verify that the soil meets the Jicarilla EPO requirements, 100 ppm TPH, 10 ppm benzene and 50 ppm BTEX.

Should you have any additional questions, please feel free to contact me at 326-9235 in our Farmington office.

Sincerely,

Brittany D Benko
Environmental Coordinator

cc: New Mexico Oil Conservation Division
1000 Rio Brazos Rd
Aztec, NM 87410
Attn: Mr. Denny Foust