

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 039 2740

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Pure Resources	Contact	Jeff Pickett
Address	463 Turner Drive, Unit 101, Durango, Co. 81303	Telephone No.	(970) 259-1374
Facility Name	Rincon Unit 159P	Facility Type	Drilling

Surface Owner	BLM	Mineral Owner	BLM	Lease No.	NMSF079404A
---------------	-----	---------------	-----	-----------	-------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	18	27-N	6-W	705'	N	335'	W	Rio Arriba

Latitude _____ Longitude _____

NATURE OF RELEASE



Type of Release	Fresh Drilling Water	Volume of Release	Esti 50 BBL	Volume Recovered	0%
Source of Release	Blow Pit off blooie line	Date and Hour of Occurrence	11:00 AM	Date and Hour of Discovery	11:30 AM
Was Immediate Notice Given?	X <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Bryce Barlan of the BLM		
By Whom?	Jeff Pickett	Date and Hour	11/24/03 13:00 HR		
Was a Watercourse Reached?	X <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	Estimated 40 to 50 bbl		

If a Watercourse was Impacted, Describe Fully.* Water leaked past drill pit; down the side of the rim rock 90' and then into dry wash where it soaked into the sand immediately.

Describe Cause of Problem and Remedial Action Taken.*
Air discharge from blooie line compromised berm integrity and leaked into sandstone.
Reinforced berm with more material: and then relined berm.

Describe Area Affected and Cleanup Action Taken.*
Water soaked into affected area; no clean up action taken at this time waiting on recommendation from the BLM. Water samples from drill pit have been taken for analysis.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jeff Pickett	Approved by District Supervisor:  for Frank Chavez	
Title: Production Foreman	Approval Date: 12/04/03	Expiration Date:
E-mail Address: jpickett@pureresources.com	Conditions of Approval: File water analysis, meet BLM requirements	Attached <input type="checkbox"/>
Date: 11/25/03	Phone: 9702591374	Additional action may be required

* Attach Additional Sheets If Necessary

N DGF 033 2929761