

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised June 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

3003906793

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Burlington Resources	Contact	Bruce Gantner
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	(505) 326-9700
Facility Name	HARVEY A 3	Facility Type	Gas Well

Surface Owner	State	Mineral Owner	State	Lease No.	E-2825-10-NM
---------------	-------	---------------	-------	-----------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	32	027N	007W	890	South	1650	East	Rio Arriba

NATURE OF RELEASE

Type of Release	Frac Flowback Water	Volume of Release	30 BBLS.	Volume Recovered	0 BBLS.
Source of Release	Wellhead	Date and Hour of Occurrence	0/15/2004 11:00:00 AM	Date and Hour of Discovery	10/15/2004 11:00:00 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Monica Kuehling		
By Whom?	Bruce Gantner	Date and Hour	10/15/2004 12:40:00 P		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully.*

NA

Describe Cause of Problem and Remedial Action Taken.*

While attempting to run a frac string and packer, a frac plug failed. This allowed approximately 30 barrels of frac flowback fluid to be released through the frac string. The released fluid consisted mainly of 2% KCl water.

Describe Area Affected and Cleanup Action Taken.*

An estimated 10 bbls of fluid stayed on location and an estimated 20 bbls of fluid left location and travelled approximately 1000 feet. No fluid was recovered. Plans are to monitor the impacted soils and rake if necessary to break up any crust that may form.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>EJ Hasely</i>		
Printed Name:	Ed Hasely		
Title: Environmental Representative	Approval Date:	11/04/04	
E-mail Address: lhasely@br-inc.com or gwurtz@br-inc.com	Conditions of Approval:	Expiration Date:	
Date:	Phone: (505) 326-9841 or 9537	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

n DG-F0429548566

