


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised June 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form



**Release Notification and Corrective Action**

**OPERATOR**

Initial Report ☒ Final Report

Name of Company	Burlington Resources	Contact	Ed Hasely
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	(505) 326-9841
Facility Name	SUNRAY J 1	Facility Type	Gas Well

Surface Owner	Federal	Mineral Owner	Federal	Lease No.	NMNM-03195
---------------	---------	---------------	---------	-----------	------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	07	030N	010W	1090	South	990	West	San Juan

**NATURE OF RELEASE**

Type of Release	Condensate	Volume of Release	80 BBLS.	Volume Recovered	0 BBLS.
Source of Release	Condensate Tank	Date and Hour of Occurrence	7/28/2004	Date and Hour of Discovery	7/28/2004
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust		
By Whom?	Ed Hasely	Date and Hour	7/28/2004 2:30:00 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully.\*  
NA

Describe Cause of Problem and Remedial Action Taken.\*  
A separator malfunction caused produced water to dump to the condensate tank. The condensate tank overflowed, floating out 80 bbls of condensate.

Describe Area Affected and Cleanup Action Taken.\*  
The tank was removed and the impacted soils were excavated. An area of approximately 30 ft by 30 ft was excavated to a depth of 30 ft and landfarmed on the Sunray J #210 well location. A PID was used to show that the side walls and bottom of the excavation tested clean.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Ed Hasely</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Ed Hasely	Approved by District Supervisor: <i>Denny Foust for Frank Chavez</i>	
Title: Environmental Representative	Approval Date: <i>8/10/04</i>	Expiration Date:
E-mail Address: lhasely@br-inc.com or gwurtz@br-inc.com	Conditions of Approval: <i>Remediate landfarm</i>	Attached <input type="checkbox"/>
Date: <i>8/4/04</i> Phone: (505) 326-9841 or 9537		

\* Attach Additional Sheets If Necessary

*NDGF0421533823*